



ENGINE Requirements Status

Prepared for Nassau Editora, Radio E Televisao Ltda Current
 Reg#: PR-GJS Original Airworthiness Date: 07/21/1996
 Make: HONEYWELL Total Time: 7034.4
 Model: TFE731-40-1C Total Cycles: 3829
 Serial#: P-115122 Due Out: 03/09/2018
 Position: 2
 Entered Into Service:

Tracker

ATA 72 Engine														
Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining	
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date		Hrs
	150 To 250 Hour Periodic			200.0			6979.4			09/05/17	7179.4			145.0
	Oil Filter And SOAP													
	500 To 650 Hour Periodic			600.0			6848.9	3752	12/30/16	7448.9			414.5	
	500 To 850 Hour Periodic			800.0			6848.9	3752	12/30/16	7648.9			614.5	
	1000 To 1300 Hour Periodic			1200.0			6848.9	3752	12/30/16	8048.9			1014.5	
	Oil Change													
	1500 To 1650 Hour Periodic			1600.0			6848.9	3752	12/30/16	8448.9			1414.5	
	Major Periodic Inspection			3500.0			6848.9	3752	12/30/16	10348.9			3314.5	
	Compressor Zone Inspection						4334.1		05/04/07					
* NOTE: Needs to complete more bulletins to go to 7000 Hour freq. Due at next MPI														
	Fan Rotor Disc Replace	3067022-1	5-03229-5366			20000			07/21/96	20000			16171	
* NOTE: ASSEMBLY P/N 3067023-1														
	Fan Spinner Replace	3060156-2	960811400563			20000			07/21/96	20000			16171	
	Low Pressure First Stage Axial Compressor Disc Replace	3072395-3	5-03160-3996			7500			07/21/96	7500			3671	
* NOTE: ASSEMBLY P/N 3070440-19														
	Low Pressure Second Stage Axial Compressor Disc Replace	3072396-4	5-03160-3520			10000			07/21/96	10000			6171	
* NOTE: ASSEMBLY P/N 3072416-12														
	Low Pressure Third Stage Axial Compressor Disc Replace	3072397-4	960316001771			10000			07/21/96	10000			6171	
* NOTE: ASSEMBLY P/N 3072417-11														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

ATA 72 Engine

Code	Description	Part#	Serial#	Frequency		Last Compliance		Next Due		Remaining	
				Hrs	Cyc Mos	Hrs	Cyc	Date	Hrs	Cyc	Date
	Low Pressure Fourth Stage Axial Compressor Disc Replace	3075326-5	6-03501-442	20000		07/21/96		20000			16171
* NOTE: ASSEMBLY P/N 3075351-12											
	High Pressure Compressor Impeller Replace	3060371-1	060322902462	8000		05/04/07	4334.1	2350	10350		6521
	High Pressure Turbine Forward Seal Plate Replace	3060514-1	5-03229-3169	10000		07/21/96		10000			6171
	High Pressure Turbine Rotor Replace	3060841-1	061217200675	10000		03/09/07	4334.1	2350	12350		8521
* NOTE: ASSEMBLY P/N 3060555-5											
	High Pressure Turbine Blades Rplc Due Only At MPI See SB 72-5172; Marking Factor 925, Blade Limit 11	3060556-1				12/30/16	6848.9	3752			
* NOTE: INSTALLED 56 NEW BLADES @ TSN 6848.9 CSN 3752											
	High Pressure Turbine Rotating Seal Replace	3060698-1	5-19033-451	7000		07/21/96		7000			3171
	Low Pressure First Stage Turbine Rotor Disc Replace	3060625-1	950322903547	12000		07/21/96		12000			8171
* NOTE: ASSEMBLY P/N 3060610-3											
	1ST Stage LP Turbine Blades Due Only At MPI See SB 72-5172; Marking Factor 900, Blade Limit 10	3060612				07/21/96					
* NOTE: 64 blades have 8 marks as of 12/30/16 @ 6848.9 Hrs											
	Low Pressure Second Stage Turbine Rotor Disc Replace	3060611-1	5-03229-2849	12000		07/21/96		12000			8171
* NOTE: ASSEMBLY P/N 3060608-2											
	2ND Stage LP Turbine Blades Due Only At MPI See SB 72-5172; Marking Factor 900, Blade Limit 10	3075424				07/21/96					
* NOTE: 52 blades have 8 marks as of 12/30/16 @ 6848.9 Hrs											
	Low Pressure Third Stage Turbine Rotor Disc Replace	3060671-2	950322903956	12000		07/21/96		12000			8171
* NOTE: ASSEMBLY P/N 3060626-6											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

ATA 72 Engine

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	
	3RD Stage LP Turbine Blades Rplc <i>Due Only At MPI See SB 72-5172; Marking Factor 790, Blade Limit 10</i>	3061823-2					6848.9	3752	12/30/16				
* NOTE: INSTALLED 56 NEW BLADES @ TSN 6848.9 CSN 3752													
	Fan Drive Shaft Replace <i>No Life Limit At This Time</i>	3060180-2	061366304320				4334.1	2350	03/09/07				
	Tie Rod Replace <i>No Life Limit At This Time</i>	3074744-1	981119500167 TSN/TSO CSN/CSO 2447.2 2157				2499.0	1239	12/31/03				
* NOTE: PARTS CARD NOT UPDATED WITH ENGINE S/N, BUT INFO IS ON THE LIFE LIMITED PARTS CHANGE RECORD													
	High Pressure Shouldered Shaft Replace <i>No Life Limit At This Time</i>	3060366-1	96P10247						07/21/96				
	High Pressure Turbine Forward Shaft Coupling Replace <i>No Life Limit At This Time</i>	3060502-2	96P09578						07/21/96				
	High Pressure Turbine Aft Shaft Coupling Replace <i>No Life Limit At This Time</i>	3060599-2	96P10585						07/21/96				
	Combustion Chamber Plenum Case Replace <i>No Life Limit At This Time</i>	3060534-3	96P00884						07/21/96				
	Low Pressure Turbine First Stage Nozzle Seal (A5) Replace <i>No Life Limit At This Time</i>	3073765-12	99P20632 TSN/TSO CSN/CSO 3897.7 1401				4334.1	2350	03/09/07				
* NOTE: ASSEMBLY P/N 3060666-7													
	Low Pressure Turbine First Stage Nozzle Seal Support Replace <i>No Life Limit At This Time</i>	3060693-1	99P22357 TSN/TSO CSN/CSO 3897.7 1401				4334.1	2350	03/09/07				
* NOTE: ASSEMBLY P/N 3060666-7													
	Turbine Interstage Transition Duct Replace <i>No Life Limit At This Time</i>	3060694-8	00P28364 TSN/TSO CSN/CSO 7133.0 4911				6848.9	3752	12/30/16				

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.

Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.

Green indicates the items baseline value used in next due calculation.

Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS

Total Time: 7034.4

Total Cycles: 3829

ATA 72 Engine

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	Low Pressure Turbine First Stage Nozzle Assembly Replace <i>No Life Limit At This Time</i>	3060666-9 TSN/TSO CSN/CSO	07P06554 2470.0 828				6848.9	3752	12/30/16						
	Accessory Gearbox Assembly Replace <i>No Life Limit At This Time</i>	3060827-2	S199						07/21/96						
	Transfer Gearbox <i>No Life Limit At This Time</i>	3070093													

ATA 73 Engine Fuel and Control

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	Fuel Pump Replace <i>No Life Limit At This Time</i>	3060760-3	0324				2065.8	976	03/16/03						
	Fuel Control Assembly Replace <i>No Life Limit At This Time</i>	3070800-49	15018				6848.9	3752	12/30/16						

ATA 76 Engine Controls

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	DEEC (Digital Electronic Engine Control) Replace <i>No Life Limit At This Time</i>	2118882-4006	117-W0014				6332.0		08/20/14						

ATA 79 Engine Oil

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	Oil Lube Pump Replace <i>No Life Limit At This Time</i>	3060785-1	071405700290				4334.1	2350	05/04/07						

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829



ENGINE Airworthiness Directives Status Tracker

Prepared for Nassau Editora, Radio E Televisao Ltda Current
 Reg#: PR-GJS Original Airworthiness Date: 07/21/1996
 Entered Into Service:
 Make: HONEYWELL Total Time: 7034.4
 Model: TFE731-40-1C Total Cycles: 3829
 Serial#: P-115122 Due Out: 03/09/2018
 Position: 2
 Biweekly #: 2019-1 Biweekly Date: 01/06/2019

Engine ADs		Revision/		Description		Compliance		Frequency		Last Compliance		Remaining		
Number	Date					Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
2008-02-19	03/06/2008	Prevent Uncontained Failure Of The HP Turbine Rotor Assembly SB 72-3720/72-5185		NLT 100/4300/3300 CYCLES							07/13/2009			
* NOTE: NA BY S/N INSTALLED														
2012-16-14	10/01/2012	2ND Stage Lpt2 Rotor Blades Failure SB 72-5221		NLT 3000 HOURS, 5 YRS OR MPI							01/15/2013			
* NOTE: NA														
2014-12-52	07/28/2014	Prevent Lpt2 Blade Failure, Multiple Engine In-flight Shutdowns SB 72-a3792, 72-a5242		PRIOR TO FLIGHT							08/20/2014			
* NOTE: NA DUE TO BLADES HAVE LESS THAN 250 HOURS TSN														
2014-12-52E	06/10/2014	Prevent Lpt2 Blade Failure, Multiple Engine In-flight Shutdowns Superseded		SUPERSEDED							07/28/2014			
2017-20-01	11/02/2017	To Prevent Uncontained Failure Of The Engine Fan Disk P/N 3060287-2 SB TFE731-72-5256		SEE AD							7034.4 3829 03/09/2018			
* NOTE: N/A - affected equipment not installed														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books
 Imported from Customer's Tracking System for Forecasting Purposes.

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.



ENGINE Service Information Status

Prepared for Nassau Editora, Radio E Televisao Ltda
 Reg#: PR-GJS Original Airworthiness Date: 07/21/1996
 Entered Into Service:
 Make: HONEYWELL Total Time: 7034.4
 Model: TFE731-40-1C Total Cycles: 3829
 Serial#: P-115122 Due Out: 03/09/2018
 Position: 2

Tracker

Service Bulletins												
Number	Revision/ Date	Description	Compliance	Frequency		Last Compliance		Remaining				
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5101	Rev:6 05/15/2007	Service Life Limits Of Critical Life Limited Components	RECOMMENDED				6848.9	3752	12/30/2016			
* NOTE: R6												
72-5109	Rev:INITIAL 12/11/1996	Install Packings, PN S9413-036 And Seals, PN 3075506-2, On Tower Shaft Oil Transfer Tube	RECOMMENDED						05/04/2007			
* NOTE: PCW												
72-5110	Rev:INITIAL 12/04/1997	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED									
72-5110	Rev:1 03/28/2007	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED									
72-5110	Rev:2 02/12/2009	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED									
72-5111	Rev:INITIAL 12/23/1997	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED						03/18/1998			
* NOTE: R0												
72-5111	Rev:1 02/09/1999	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED									
72-5111	Rev:2 04/09/2001	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED									
72-5111	Rev:3 03/28/2007	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED									

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Printed on 11/11/2019
 11:2:32AM by ROTH

Service Bulletins

Number	Revision/		Description	Compliance			Frequency			Last Compliance			Remaining		
	Date			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5112	Rev:INITIAL 03/06/1998		Bank Engine Model Conversions	OPTIONAL											
72-5112	Rev:1 09/20/1999		Bank Engine Model Conversions	OPTIONAL											
72-5112	Rev:2 09/15/2006		Bank Engine Model Conversions	OPTIONAL											
72-5112	Rev:3 06/07/2007		Bank Engine Model Conversions	OPTIONAL											
72-5115	Rev:1 04/03/2007		Replace Bolts That Secure The LP Compressor Case Assembly To The Combustion Chamber (Plenum) Case	RECOMMENDED							05/04/2007				
* NOTE: PCW R1															
72-5117	Rev:1 03/04/1998		Install/Rework Accessory Drive Gearbox Assembly With An Air-Oil Separator (Five Piece)(Inactive For Further Accomplishment)	INACTIVE							05/04/2007				
* NOTE: R1 NA															
72-5117	Rev:2 05/01/1998		Install/Rework Accessory Drive Gearbox Assembly With An Air-Oil Separator (Five Piece)(Inactive For Further Accomplishment)	INACTIVE											
72-5120	Rev:1 03/28/2007		Replace The No. 4 High Pressure Rotor Roller Bearing	RECOMMENDED							05/04/2007				
* NOTE: PCW R1 03/18/1998															
72-5122	Rev:INITIAL 03/11/1998		Replacement Of Combustion Chamber On Specific Engines	RECOMMENDED							05/04/2007				
* NOTE: PCW															
72-5124	Rev:INITIAL 03/18/1998		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED											
72-5124	Rev:1 07/02/1998		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED											
72-5124	Rev:2 01/22/2008		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books Imported from Customer's Tracking System for Forecasting Purposes.

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining							
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos					
72-5126	Rev:1 06/27/2003	Inspect/Rework/Install Oil Filter Cover, PN 3072231-2/1-3 To PN 3072231-5												05/04/2007					
* NOTE: R1 PCW 01/05/2004																			
72-5126	Rev:2 02/13/2008	Inspect/Rework/Install Oil Filter Cover, PN 3072231-2/1-3 To PN 3072231-5																	
72-5127	Rev:1 01/23/2002	Servicing With Mobil 254 Oil (Inactive For Further Accomplishment)													05/04/2007				
* NOTE: NA R1																			
72-5131	Rev:INITIAL 09/30/1999	Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, PN 3074108-2																	
72-5131	Rev:1 11/01/2007	Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, PN 3074108-2													05/04/2007				
* NOTE: NA																			
72-5132	Rev:1 02/12/2008	Install (Oil) Filter Element PN 3070945-1 (Sampling Kit, PN 831044-1)													04/17/2008				
* NOTE: R1																			
72-5134	Rev:INITIAL 06/08/2000	Rework / Replace Fan Rotor Assembly																	
72-5134	Rev:1 03/14/2003	Rework / Replace Fan Rotor Assembly																	
72-5134	Rev:2 02/13/2008	Rework / Replace Fan Rotor Assembly																	
72-5136	Rev:INITIAL 10/07/1999	Install Fan Stator Vane(s), PN 3060378-1/3060379-1 (As Applicable), And Associated Shroud Grommet(s) Or Replace The Fan Stator Vane Assembly																	
72-5136	Rev:1 02/05/2008	Install Fan Stator Vane(s), PN 3060378-1/3060379-1 (As Applicable), And Associated Shroud Grommet(s) Or Replace The Fan Stator Vane Assembly																	
72-5137	Rev:INITIAL 08/08/2001	Install High Pressure (HP) Turbine Rotor Assembly, PN 3060555-4													05/04/2007				
* NOTE: R0																			

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining						
			PN	RECOMMENDED	OPTIONAL	Hrs	Cyc	Mos	Date	Hrs	Cyc	Mos	Hrs	Cyc	Mos			
72-5137	Rev:1 12/14/2007	Install High Pressure (HP) Turbine Rotor Assembly, PN 3060555-4	PN	RECOMMENDED														
72-5138	Rev:1 12/14/2007	Installation Of Turbine Interstage Transition (ITT) Duct And Engine Clevis		OPTIONAL														
72-5138	Rev:INITIAL 01/22/2001	Installation Of Turbine Interstage Transition (ITT) Duct And Engine Clevis		OPTIONAL														
72-5140	Rev:INITIAL 08/27/2000	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL														
72-5140	Rev:1 09/20/2004	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL														
72-5140	Rev:2 02/24/2009	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL														
72-5140	Rev:3 05/11/2009	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL														
72-5141	Rev:1 09/27/2002	Inspection/Replacement (As Required) Of Threaded Ends Tie Rod (Low Pressure (LP) Tie Rod), Part Number 3074744-1		RECOMMENDED														05/04/2007
* NOTE: R1																		
72-5141	Rev:2 06/11/2007	Inspection/Replacement (As Required) Of Threaded Ends Tie Rod (Low Pressure (LP) Tie Rod), Part Number 3074744-1		RECOMMENDED														
72-5142	Rev:INITIAL 07/13/2001	Installation Of HP Turbine Nozzle Segments, PN 3060840-1/-2/-3		RECOMMENDED														
72-5142	Rev:1 06/07/2007	Installation Of HP Turbine Nozzle Segments, PN 3060840-1/-2/-3		RECOMMENDED														
72-5145	Rev:INITIAL 03/01/2001	Consumables Installation Kits		INFORMATIONAL														
72-5145	Rev:1 05/09/2003	Consumables Installation Kits		INFORMATIONAL														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5145	Rev:2 03/28/2007	Consumables Installation Kits	INFORMATIONAL											
72-5147	Rev:4 03/28/2007	Replace #4 And #5 Segmented Carbon Seals And Associated Vent/ Oil System Components	RECOMMENDED							05/04/2007				
* NOTE: R4 PCW 01/05/2004														
72-5147	Rev:5 01/28/2009	Replace #4 And #5 Segmented Carbon Seals And Associated Vent/ Oil System Components	RECOMMENDED											
72-5148	Rev:INITIAL 03/23/2001	Provide Authority For Installation Of An Alternate Transfer Gearbox Housing Assembly	OPTIONAL											
72-5148	Rev:1 12/14/2007	Provide Authority For Installation Of An Alternate Transfer Gearbox Housing Assembly	OPTIONAL											
72-5150	Rev:2 02/10/2006	Replace The Hoisting Bracket On The Fan Duct Set, PN 3072420-13 (Upper Half), On Specific Identified Engines	RECOMMENDED							05/04/2007				
* NOTE: R2 NA														
72-5150	Rev:3 06/11/2007	Replace The Hoisting Bracket On The Fan Duct Set, PN 3072420-13 (Upper Half), On Specific Identified Engines	RECOMMENDED											
72-5151	Rev:INITIAL 11/09/2001	Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer	RECOMMENDED							05/04/2007				
* NOTE: R0 NA														
72-5151	Rev:1 10/31/2007	Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer	RECOMMENDED											
72-5152	Rev:1 04/29/2002	Replace Outer Transition Liner, PN 3060573-1, With Part Number 3060573-2 Or 3067016-1	RECOMMENDED							05/04/2007				
* NOTE: R1 PCW 01/05/2004														
72-5152	Rev:2 08/17/2007	Replace Outer Transition Liner, PN 3060573-1, With Part Number 3060573-2 Or 3067016-1	RECOMMENDED											
72-5153	Rev:INITIAL 01/23/2007	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5153	Rev:1 05/28/2015	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											
72-5153	Rev:2 04/22/2018	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											
72-5154	Rev:1 09/27/2002	Inspection Of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1	RECOMMENDED							05/04/2007				
* NOTE: R1														
72-5154	Rev:2 11/01/2007	Inspection Of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1 <i>Recurring upon access</i>	RECOMMENDED											
72-5156	Rev:INITIAL 05/20/2003	Repositioning Of Branched Engine Harness Assembly	OPTIONAL											
72-5156	Rev:1 09/30/2005	Repositioning Of Branched Engine Harness Assembly	OPTIONAL											
72-5157	Rev:INITIAL 03/07/2003	Remove Specific Identified LP Compressor Second Stage (LPC2) Discs	RECOMMENDED							05/04/2007				
* NOTE: R0 NA														
72-5157	Rev:1 11/01/2007	Remove Specific Identified LP Compressor Second Stage (LPC2) Discs	RECOMMENDED											
72-5158	Rev:2 02/18/2005	Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention	RECOMMENDED							05/04/2007				
* NOTE: R2														
72-5158	Rev:3 03/11/2009	Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention	RECOMMENDED											
72-5159	Rev:2 05/28/2004	Install The Improved Filter By-Pass Valve Assembly PN 3060782-2	RECOMMENDED							05/04/2007				
* NOTE: R2 PCW 06/13/2003														
72-5159	Rev:3 10/26/2007	Install The Improved Filter By-Pass Valve Assembly PN 3060782-2	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			PN	RECOMMENDED	OPTIONAL	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5159	Rev:4 09/20/2012	Install The Improved Filter By-Pass Valve Assembly	PN 3060782-2	RECOMMENDED										
72-5160	Rev:INITIAL 06/05/2003	Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, PN 3060788-1		OPTIONAL										
72-5160	Rev:1 01/21/2008	Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, PN 3060788-1		OPTIONAL										
72-5162	Rev:INITIAL 02/14/2003	Replacement Of The Front Frame Assembly		OPTIONAL										
72-5163	Rev:2 06/14/2005	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED						05/04/2007				
* NOTE: R2														
72-5163	Rev:3 07/03/2008	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5163	Rev:4 11/16/2015	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5164	Rev:INITIAL 05/07/2004	Replace The Number 6 Rear Bearing Housing		OPTIONAL										
72-5164	Rev:1 12/14/2007	Replace The Number 6 Rear Bearing Housing		OPTIONAL										
72-5165	Rev:INITIAL 09/10/2003	Install An Improved LP Turbine 2ND (LPT2) Stage Nozzle Retainer And LPT2 Stage Shroud Segments		RECOMMENDED						05/04/2007				
* NOTE: R0 PCW 01/05/2004														
72-5165	Rev:1 08/17/2007	Install An Improved LP Turbine 2ND (LPT2) Stage Nozzle Retainer And LPT2 Stage Shroud Segments		RECOMMENDED										
72-5166	Rev:1 07/21/2004	Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, PN 3070151-4		RECOMMENDED						05/04/2007				
* NOTE: R1														
72-5172	Rev:5 08/07/2015	HPT And LPT Blade Hour Tracking And Recommended Blade Replacement Intervals For TFE731-20, -40, -50, -60 Series Engine Models		RECOMMENDED						6848.9	3752	12/30/2016		
* NOTE: R5														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5173	Rev:INITIAL 06/15/2005	Replace Specific Identified Helical Ring Gears, PN 3060277-2, And Inspect Associated Parts	RECOMMENDED											
72-5173	Rev:1 11/14/2005	Replace Specific Identified Helical Ring Gears, PN 3060277-2, And Inspect Associated Parts	RECOMMENDED							05/04/2007				
72-5174	Rev:INITIAL 03/05/2004	Remove Specific Identified High Pressure Turbine (HPT) Rotor Discs	RECOMMENDED							05/04/2007				
* NOTE: RO NA														
72-5174	Rev:1 12/04/2007	Remove Specific Identified High Pressure Turbine (HPT) Rotor Discs	RECOMMENDED											
72-5175	Rev:INITIAL 09/08/2004	Replace Low Pressure (LP) 3rd Stage Turbine (LPT3) Blades, PN 3060690-1, On Specific Identified LPT3 Rotor Assemblies	RECOMMENDED							05/04/2007				
* NOTE: NA														
72-5176	Rev:INITIAL 05/12/2004	Accessory Drives Section - Install Air-Oil Separator, Part No. 3075781-1 <i>Accomplishment of 72-5124 will no longer be applicable when the equipment has been modified in accordance with the accomplishment instructions outlined in this service bulletin</i>	RECOMMENDED							05/04/2007				
72-5177	Rev:INITIAL 08/10/2004	Replace Specific Identified LP Second Stage Turbine Blades (LPT2), PN 3075424-1/-2 (As Applicable)	RECOMMENDED							05/04/2007				
* NOTE: NA														
72-5178	Rev:INITIAL 10/28/2008	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2	OPTIONAL											
72-5178	Rev:1 05/11/2009	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2	OPTIONAL											
72-5178	Rev:2 08/04/2014	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2	OPTIONAL											
72-5179	Rev:INITIAL 02/16/2009	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3	OPTIONAL											
72-5179	Rev:1 05/11/2009	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3	OPTIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5179	Rev:2 07/03/2014	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3	OPTIONAL											
72-5179	Rev:3 08/04/2014	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3	OPTIONAL											
72-5181	Rev:INITIAL 06/17/2005	Rework / Install Planetary Gearshaft Assembly, PN 3060129-3, -4 To PN 3060129-7	RECOMMENDED							05/04/2007				
* NOTE: R0														
72-5181	Rev:1 07/03/2008	Rework / Install Planetary Gearshaft Assembly, PN 3060129-3, -4 To PN 3060129-7	RECOMMENDED											
72-5191	Rev:INITIAL 03/28/2007	Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly PN 3072416-15/-16	OPTIONAL											
72-5191	Rev:1 02/06/2008	Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly PN 3072416-15/-16	OPTIONAL											
72-5194	Rev:3 10/19/2012	Install Improved Design HP And LP Turbine Shrouds And Associated Hardware	RECOMMENDED						6848.9	3752	12/30/2016			
* NOTE: R3														
72-5195	Rev:INITIAL 07/16/2007	Install Low Pressure Compressor (LPC) Case Assembly PN 3074730-5	RECOMMENDED											
72-5195	Rev:1 09/19/2008	Install Low Pressure Compressor (LPC) Case Assembly PN 3074730-5	RECOMMENDED											
72-5196	Rev:INITIAL 04/29/2008	Replace / Rework Fan Stator Vane Assembly, PN 3060163-4 To PN 3060163-5 And PN 3060239-4 To PN 3060239-5 (As Applicable)	OPTIONAL											
72-5196	Rev:1 11/18/2008	Replace / Rework Fan Stator Vane Assembly, PN 3060163-4 To PN 3060163-5 And PN 3060239-4 To PN 3060239-5 (As Applicable)	OPTIONAL											
72-5197	Rev:INITIAL 09/17/2007	Install Deswir PN 3060326-4	RECOMMENDED											
72-5197	Rev:1 12/19/2008	Install Deswir PN 3060326-4	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining				
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos		
72-5198	Rev:INITIAL 09/07/2007	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5	RECOMMENDED													
72-5198	Rev:1 03/14/2008	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5	RECOMMENDED													
72-5198	Rev:2 09/19/2008	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5	RECOMMENDED													
72-5199	Rev:INITIAL 01/18/2008	Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 And LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)	RECOMMENDED													
72-5199	Rev:1 09/19/2008	Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 And LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)	RECOMMENDED													
72-5200	Rev:INITIAL 05/22/2008	Replace LP Compressor 2ND Stage Rotor Assembly, PN 3072416 With PN 3075841 <i>When LPC2 rotor disc is scrapped</i>	OPTIONAL													
72-5201	Rev:INITIAL 12/10/2008	Replace Low Pressure Compressor 4th Stage (LPC4) Case and Vane Assembly, PN 3060361-4 With PN 3060361-5	RECOMMENDED													
72-5202	Rev:INITIAL 04/21/2008	Install Improved No. 4 Segmented Carbon Seal, PN 3060437-1, And No. 5 Segmented Carbon Seal, PN 3060436-1	RECOMMENDED													
72-5203	Rev:INITIAL 04/21/2008	Install Improved No. 1 Carbon Seal, PN 3060457-1	RECOMMENDED										6848.9	3752	12/30/2016	
72-5204	Rev:1 05/11/2009	Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers	RECOMMENDED											6848.9	3752	12/30/2016
* NOTE: R1																
72-5208	Rev:INITIAL 10/23/2009	Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating Improved Design LPT3 Blades PN 3061823-2	RECOMMENDED											6848.9	3752	12/30/2016
72-5215	Rev:INITIAL 03/18/2010	Install Improved Rear Bearing Housing Support That Provides Additional Clearance To LPT3 Blades <i>Only if contact (rub) has occurred</i>	OPTIONAL													

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5216	Rev:1 10/28/2011	Install Improved Plain Encased Seal, PN 3020052-26	RECOMMENDED						6848.9	3752	12/30/2016			
* NOTE: R1														
72-5217	Rev:INITIAL 10/22/2010	Install Improved Front Frame Assembly, PN 3060421-3, PN 3061505-4, Or PN 3060439-2 <i>When the front frame assembly is replaced for cause.</i>	OPTIONAL											
72-5218	Rev:INITIAL 11/08/2010	Introduction Of New Second Stage Low Pressure Compressor Blade (LPC2), PN 3075840-3	OPTIONAL											
72-5221	Rev:INITIAL 11/11/2010	Replace Specific Low Pressure 2nd Stage Turbine Rotor Blades, PN 3075424-2, -3	RECOMMENDED								01/09/2013			
* NOTE: NA														
72-5221	Rev:1 11/02/2017	Replace Specific Low Pressure 2nd Stage Turbine Rotor Blades, PN 3075424-2, -3	RECOMMENDED											
72-5222	Rev:INITIAL 08/19/2011	Install Front Frame Assembly That Has Additional Corrosion Protection Features	RECOMMENDED											
72-5222	Rev:1 05/01/2012	Install Front Frame Assembly That Has Additional Corrosion Protection Features	RECOMMENDED											
72-5223	Rev:INITIAL 08/19/2011	Apply Protective Coating To The Aft Flange Of The Composite Bypass Duct	RECOMMENDED						6848.9	3752	12/30/2016			
* NOTE: NA BY DUCT S/N														
72-5223	Rev:1 04/20/2018	Apply Protective Coating To The Aft Flange Of The Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models	RECOMMENDED											
72-5224	Rev:INITIAL 08/19/2011	Inspect, Rework, Or Replace Composite Bypass Ducts	RECOMMENDED											
72-5224	Rev:1 04/19/2018	Inspect, Rework, Or Replace Composite Bypass Ducts On TFE731-20, -40, -50, and -60 Engine Models.	RECOMMENDED											
72-5225	Rev:INITIAL 07/22/2011	Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, PN 3072403-6	RECOMMENDED											
72-5225	Rev:1 08/17/2012	Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, PN 3072403-6	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5227	Rev:INITIAL 03/19/2014	Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals	RECOMMENDED											
72-5227	Rev:1 07/24/2015	Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals	RECOMMENDED											
72-5236	Rev:INITIAL 11/25/2013	Installation Of New Or Reworked Fan Inlet Housing	RECOMMENDED											
72-5236	Rev:1 01/23/2015	Installation Of New Or Reworked Fan Inlet Housing <i>When the fan inlet housing is no longer serviceable.</i>	OPTIONAL											
72-5247	Rev:INITIAL 07/08/2015	Replace Fan Stator Vane Assembly, PN 3060163-3, -4, -5 With PN 70060130-1	RECOMMENDED											
72-5251	Rev:INITIAL 03/25/2015	Accomplish Eddy Current Inspection Of Specific Second Stage Low Pressure Turbine (LPT2) Blades PN 3075424	RECOMMENDED											
72-5253	Rev:INITIAL 12/02/2015	Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5	RECOMMENDED											
72-5256	Rev:INITIAL 10/07/2016	Identify and Replace Specific Fan Discs, PN 3060287-2, with Suspect Shot Peened Rolled Edges	RECOMMENDED						6848.9	3752			12/30/2016	
* NOTE: NA BY DISC PN														
72-5264	Rev:INITIAL 06/08/2016	Replace Rigid Shaft Coupling, PN 3060116-1 With PN 3060116-2, On TFE731-20, -40 Engines <i>Requires Honeywell engineering authorization for incorporation.</i>	RECOMMENDED											
72-5267	Rev:INITIAL 04/22/2018	Composite Bypass Duct Optional Replacement Configurations On Specific TFE731-20, -40 Engine Models	OPTIONAL											
73-5106	Rev:INITIAL 11/05/1996	Replace Fuel Flow Meter To Flow Divider Assembly, PN 3061176-1, With PN 3061199-1	RECOMMENDED										05/04/2007	
* NOTE: PCW														
73-5107	Rev:INITIAL 06/29/1999	One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, PN 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly	RECOMMENDED										05/04/2007	
* NOTE: R0 NA														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
73-5107	Rev:1 11/16/2007	One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, PN 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly	RECOMMENDED											
73-5108	Rev:INITIAL 05/23/1997	Replace Fuel Pump, PN 3060719-10 With PN 3060760-1	OPTIONAL							05/04/2007				
* NOTE: NA														
73-5115	Rev:1 12/07/1998	Rework Fuel Pump Using Differential Pressure Indicator, PN 5911442-2	RECOMMENDED							05/04/2007				
* NOTE: R1 PCW 10/12/1999														
73-5115	Rev:2 01/25/2008	Rework Fuel Pump Using Differential Pressure Indicator, PN 5911442-2	RECOMMENDED											
73-5116	Rev:INITIAL 05/15/2000	Install Combustor to 6 O'Clock Strut Tube Assembly, PN 3061264-1	RECOMMENDED							05/04/2007				
* NOTE: R0 PCW 01/05/2004														
73-5116	Rev:1 01/25/2008	Install Combustor to 6 O'Clock Strut Tube Assembly, PN 3061264-1	RECOMMENDED											
73-5117	Rev:1 05/25/2001	Install Fuel Pump To Fuel Heat / Oil Cooler Tube Assembly, PN 3061286-1	RECOMMENDED							08/13/2001				
* NOTE: R1														
73-5118	Rev:2 03/09/1999	Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motor	RECOMMENDED							05/04/2007				
* NOTE: R2 NA														
73-5118	Rev:3 06/11/2007	Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motor	RECOMMENDED											
73-5120	Rev:INITIAL 02/11/2000	Install Fuel Manifold Flexible Hose Assemblies (Primary), PN 3061294-1	RECOMMENDED							04/13/2001				
73-5121	Rev:INITIAL 12/17/1999	Rework / Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2	RECOMMENDED							05/04/2007				
* NOTE: R0 PCW 04/13/2001														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
73-5121	Rev:1 02/22/2008	Rework / Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2	RECOMMENDED											
73-5124	Rev:INITIAL 05/25/2001	Install Clamps Between Fuel Heater Pump To Fuel Heater / Oil Cooler Tube Assembly And The Fuel Heater / Oil Cooler To Fuel Pump Tube Assembly	RECOMMENDED							08/13/2001				
* NOTE: R0														
73-5124	Rev:1 02/08/2008	Install Clamps Between Fuel Heater Pump To Fuel Heater / Oil Cooler Tube Assembly And The Fuel Heater / Oil Cooler To Fuel Pump Tube Assembly	RECOMMENDED											
73-5128	Rev:INITIAL 12/21/2001	Install Primary Fuel Tube Assembly, PN 3061203-1, And Secondary Fuel Tube Assembly, PN 3061204-1	RECOMMENDED							05/04/2007				
* NOTE: R0 PCW 01/05/2004														
73-5128	Rev:1 12/12/2007	Install Primary Fuel Tube Assembly, PN 3061203-1, And Secondary Fuel Tube Assembly, PN 3061204-1	RECOMMENDED											
73-5130	Rev:INITIAL 10/07/2002	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED							05/04/2007				
* NOTE: R0 NA														
73-5130	Rev:1 06/18/2007	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED											
73-5131	Rev:INITIAL 05/28/2004	Install Fuel Pump That Incorporates Differential Pressure Indicator, PN 5913809-2	OPTIONAL											
73-5131	Rev:1 11/14/2005	Install Fuel Pump That Incorporates Differential Pressure Indicator, PN 5913809-2	OPTIONAL											
73-5135	Rev:INITIAL 03/29/2005	Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed	RECOMMENDED							05/04/2007				
* NOTE: NA														
73-5136	Rev:INITIAL 09/12/2005	Replace Main Turbine Engine Fuel Pump Fuel Filter Element With Fuel Filter Element, PN 897830-1	RECOMMENDED							6848.9	3752	12/30/2016		
73-5137	Rev:INITIAL 03/15/2006	Replace Specific Identified Main Turbine Engine Fuel Pumps (Fuel Pump), PN 3060760-4	RECOMMENDED									05/04/2007		
* NOTE: NA														

Data in this report is provided for planning purposes only
and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7034.4
 Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			RECOMMENDED	OPTIONAL	RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
73-5138	Rev:INITIAL 03/21/2006	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED							04/28/2006				
* NOTE: NA														
73-5140	Rev:INITIAL 05/31/2013	Install Motive Flow Fuel Pump, PN 70060003-1	OPTIONAL											
73-5141	Rev:1 06/21/2012	Install Improved Main Turbine Engine Fuel Control Assembly, PN 3070800-47 and -49 <i>When the main turbine engine fuel control assembly is replaced for cause.</i>	OPTIONAL						6848.9	3752	12/30/2016			
* NOTE: R1														
73-5146	Rev:INITIAL 05/04/2017	Install Improved Fuel Control Assembly (FCA), P/N 3070800-28, -30, -37, -47, -69, And -79, With Improved Solenoid Attachment Screws On TFE731-20, -40, -50, And -60 Engine Models	RECOMMENDED											
73-5146	Rev:1 01/24/2018	Install Improved Fuel Control Assembly (FCA), P/N 3070800-28, -30, -37, -47, -69, And -79, With Improved Solenoid Attachment Screws On TFE731-20, -40, -50, And -60 Engine Models	RECOMMENDED											
75-5101	Rev:INITIAL 11/12/2003	Install Low Pressure (LP) Bleed Duct, PN 3060770-2 Or 3060770-3, And Outer Flange, PN 3071244-2 (As Applicable)	OPTIONAL											
76-5107	Rev:INITIAL 12/24/1997	Install Digital Electronic Engine Control (DEEC) PN 2118882-4003	OPTIONAL								05/04/2007			
* NOTE: PCW														
76-5109	Rev:2 09/20/2004	Install / Rework Solenoid Controller Valve, PN 109696-5-1 To PN 109696-6-1	OPTIONAL								05/04/2007			
* NOTE: PCW R2														
76-5110	Rev:INITIAL 06/17/1998	Install Digital Electronic Engine Control (DEEC) PN 2118882-4004	RECOMMENDED								05/04/2007			
* NOTE: PCW														
76-5112	Rev:INITIAL 09/15/1999	Install Digital Electronic Engine Control (DEEC) PN 2118882-4005	RECOMMENDED								05/04/2007			
* NOTE: PCW														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining					
			PN	RECOMMENDED	OPTIONAL	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos			
76-5115	Rev:1 06/18/2002	Install Digital Electronic Engine Control (DEEC) PN 2118882-4006	PN	RECOMMENDED	OPTIONAL									01/05/2004			
* NOTE: R1																	
76-5116	Rev:INITIAL 10/28/2002	Rework / Install Surge Bleed Valve, PN 978812-7-1	PN	RECOMMENDED	OPTIONAL												
76-5116	Rev:1 01/30/2008	Rework / Install Surge Bleed Valve, PN 978812-7-1	PN	RECOMMENDED	OPTIONAL												
77-5101	Rev:1 01/15/1997	Replace N1 Compensator On Specific Identified Engines	PN	RECOMMENDED	RECOMMENDED									03/18/1998			
* NOTE: R1																	
77-5105	Rev:2 02/04/2000	Install Improved Thermocouple Harness	PN	RECOMMENDED	RECOMMENDED									05/04/2007			
* NOTE: R2 PCW 04/24/2003																	
77-5108	Rev:INITIAL 04/20/2005	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security	PN	RECOMMENDED	RECOMMENDED									05/04/2007			
* NOTE: R0																	
77-5108	Rev:1 06/01/2005	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security	PN	RECOMMENDED	RECOMMENDED												
77-5108	Rev:2 03/06/2006	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security	PN	RECOMMENDED	RECOMMENDED												
77-5108	Rev:3 08/11/2008	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security	PN	RECOMMENDED	RECOMMENDED												
77-5109	Rev:INITIAL 08/18/2008	Install Improved N1 Lead Assembly, PN 3060718-4 Or PN 3060729-4 <i>When N1 lead assembly is replaced for cause.</i>	PN	OPTIONAL	OPTIONAL									6848.9	3752	12/30/2016	
79-5104	Rev:2 09/20/2004	Replace Oil Flow Reduction Valve (ORV)	PN	OPTIONAL	OPTIONAL									05/04/2007			
* NOTE: PCW R2																	

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining						
			Compliance	Hrs	Cyc	Mos	Hrs	Cyc	Mos	Date	Hrs	Cyc	Mos					
79-5105	Rev:1 03/28/2007	Oil Lube Pump, PN 3060701-4/-5 To PN 3060701-6	RECOMMENDED															
* NOTE: PCW R1																		
79-5106	Rev:5 12/11/2002	Install An Improved Oil Drainback System	RECOMMENDED															
* NOTE: R5 PCW 05/01/2001																		
79-5106	Rev:6 03/12/2008	Install An Improved Oil Drainback System	RECOMMENDED															
79-5106	Rev:7 02/06/2013	Install An Improved Oil Drainback System	RECOMMENDED															
79-5107	Rev:INITIAL 04/10/2007	Install Loop Clamps On Oil Tubes To Prevent Vibration And Chaffing	RECOMMENDED															
79-5110	Rev:INITIAL 02/28/2001	Replace / Rework Oil Tank Filler Plug For Use With Lockwire	OPTIONAL															
79-5110	Rev:1 03/12/2008	Replace / Rework Oil Tank Filler Plug For Use With Lockwire	OPTIONAL															
79-5110	Rev:2 05/09/2018	Replace / Rework Oil Tank Filler Plug For Use With Lockwire On TFE731-20, -40, -50, -60 Model Engines	OPTIONAL															
79-5111	Rev:INITIAL 10/01/2001	Install Oil Lube Pump, PN 3060701-7	RECOMMENDED															
* NOTE: R0 NA																		
79-5111	Rev:1 03/28/2007	Install Oil Lube Pump, PN 3060701-7	RECOMMENDED															
79-5112	Rev:2 03/28/2007	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump), Part No's. 3060785-1/-2	RECOMMENDED															
* NOTE: R2 PCW 01/05/2004																		
79-5112	Rev:3 04/12/2012	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump), Part No's. 3060785-1/-2	RECOMMENDED															

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos	Hrs	Cyc
79-5113	Rev:INITIAL 06/26/2002	Install Oil Supply Tube Assembly, Part Number 3061207-6 Or 3061208-6	RECOMMENDED								01/05/2004			
* NOTE: R0														
79-5113	Rev:1 03/28/2007	Install Oil Supply Tube Assembly, Part Number 3061207-6 Or 3061208-6	RECOMMENDED								05/04/2007			
* NOTE: PCW R1														
79-5114	Rev:INITIAL 11/12/2003	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5114	Rev:1 04/26/2004	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5114	Rev:2 03/12/2008	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5115	Rev:INITIAL 03/12/2004	Replace Oil Tank Sight Glass Decal, PN 461-512-9001	OPTIONAL											
79-5116	Rev:INITIAL 01/05/2007	Replace Seal On By-Pass Duct Panel, PN 3061101-1/-2/-4/-5	OPTIONAL											
79-5117	Rev:INITIAL 09/10/2007	Replace The Seal(s) On Bottom Panel PN 3060947-2 Through -11	OPTIONAL											
79-5118	Rev:INITIAL 06/18/2007	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5118	Rev:1 09/23/2008	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5118	Rev:2 02/06/2013	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5119	Rev:INITIAL 08/26/2009	Install Improved Packings In Oil Lube And Scavenge Pump, PN 3060785-1, -2 <i>Next access is defined as the removal of the oil pressure regulator</i>	OPTIONAL											
79-5121	Rev:INITIAL 02/29/2012	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) PN 3060785-3 <i>When replaced for cause.</i>	OPTIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.

Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.

Green indicates the items baseline value used in next due calculation.

Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS

Total Time: 7034.4

Total Cycles: 3829

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
79-5125	Rev:INITIAL 07/25/2013	Install New Forward No. 6 Bearing Oil Supply Tube Assembly, PN 3060900-2, And Mid No. 6 Bearing Oil Supply Tube Assembly, PN 3060901-6	RECOMMENDED											
79-5127	Rev:INITIAL 03/14/2014	Install Two-Piece Air-Oil Cooler Supply Tube Assembly	RECOMMENDED											
79-5129	Rev:INITIAL 05/09/2018	Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing On TFE731-20, -40, -60 Model Engines	RECOMMENDED											
A72-5121	Rev:INITIAL 01/21/1998	One Time Oil And Filter Resample	RECOMMENDED							12/08/2003				
* NOTE: NA														
A72-5185	Rev:INITIAL 07/05/2006	Inspect / Replace Specific Identified High Pressure (HP) Turbine Rotor Disks, Part No. 3060841-1	ALERT							05/04/2007				
* NOTE: NA														
A72-5240	Rev:INITIAL 06/25/2014	Inspect Or Replace Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Engines affected by SB 72-A5242 only	ALERT							08/20/2014				
* NOTE: R0 NA														
A72-5242	Rev:1 06/25/2014	Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades	ALERT							08/20/2014				
* NOTE: R1 NA														
A72-5242	Rev:2 08/29/2014	Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades	ALERT											
A72-5246	Rev:INITIAL 06/25/2014	Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Engine affected by SB 72-A5240, 72-A5241	ALERT							08/20/2014				
* NOTE: R0 NA														
A73-5110	Rev:INITIAL 03/16/1998	Inspection Of Secondary Fuel Line Manifold For Chaffing/ Cutting	ALERT							05/04/2007				
* NOTE: pcw														
A73-5114	Rev:INITIAL 07/30/1998	Inspect Fuel Pump To Fuel Heater / Oil Cooler Tube Assembly, PN 3061174-1, For Fretting (Chafing)	ALERT							09/02/1998				

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.