



ENGINE Requirements Status

Prepared for Nassau Editora, Radio E Televisao Ltda Current
 Reg#: PR-GJS Original Airworthiness Date: 03/18/1996
 Make: HONEYWELL Total Time: 7179.8
 Model: TFE731-40-1C Total Cycles: 3909
 Serial#: P-115111 Due Out: 03/09/2018
 Position: 3
 Entered Into Service:

Tracker

ATA 72 Engine																
Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining			
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date		Hrs	Cyc	Mos
	150 To 250 Hour Periodic			200.0			7124.8			09/05/17	7324.8			145.0		
	Oil Filter And SOAP															
	500 To 650 Hour Periodic			600.0			6994.4	3832	12/30/16	7594.4				414.6		
	500 To 850 Hour Periodic			800.0			6994.4	3832	12/30/16	7794.4				614.6		
	1000 To 1300 Hour Periodic			1200.0			6994.4	3832	12/30/16	8194.4				1014.6		
	Oil Change															
	1500 To 1650 Hour Periodic			1600.0			6994.4	3832	12/30/16	8594.4				1414.6		
	Major Periodic Inspection			3500.0			6994.4	3832	12/30/16	10494.4				3314.6		
	Compressor Zone Inspection			6000.0			4653.9		08/29/07	10653.9				3474.1		
	Fan Rotor Disc Replace	3067022-1	5-03229-2674		20000					03/18/96	20000			16091		
	Fan Spinner Replace	3060156-2	5-08114-154		20000					03/18/96	20000			16091		
	Low Pressure First Stage Axial Compressor Disc Replace	3072395-3	5-03160-2429		7500					03/18/96	7500			3591		
	Low Pressure Second Stage Axial Compressor Disc Replace	3072396-4	5-03160-2517		10000					03/18/96	10000			6091		
	Low Pressure Third Stage Axial Compressor Disc Replace	3072397-4	5-03160-2590		10000					03/18/96	10000			6091		
	Low Pressure Fourth Stage Axial Compressor Disc Replace	3075326-5	5-03501-3270		20000					03/18/96	20000			16091		
	High Pressure Compressor Impeller Replace	3060371-1	5-23315-557		8000					03/18/96	8000			4091		
	High Pressure Turbine Forward Seal Plate Replace	3060514-1	4-03229-3756		10000					03/18/96	10000			6091		

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Printed on 01/11/2019
 11:03:25AM by ROTH

ATA 72 Engine

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	
3060841-1	High Pressure Turbine Rotor Replace	3060841-1	061217200478	10000			4653.9	2543	08/30/07	12543			8634
* NOTE: ASSEMBLY P/N 3060555-5													
3060556-1	High Pressure Turbine Blades Rplc Due Only At MPI See SB 72-5172; Marking Factor 925, Blade Limit 11	3060556-1					4653.9	2543	08/30/07				
* NOTE: 12/30/16 - 56 blades with 3 marks @ ETSN 6994.4													
3060698-1	High Pressure Turbine Rotating Seal Replace	3060698-1	4-19033-205	7000					03/18/96	7000			3091
3060625-1	Low Pressure First Stage Turbine Rotor Disc Replace	3060625-1	4-03229-2602	12000					03/18/96	12000			8091
* NOTE: ASSEMBLY P/N 3060610-3													
3060612	1ST Stage LP Turbine Blades Due Only At MPI See SB 72-5172; Marking Factor 900, Blade Limit 10	3060612							03/18/96				
* NOTE: 12/30/16 - 64 blades with 8 marks @ ETSN 6994.4													
3060611-1	Low Pressure Second Stage Turbine Rotor Disc Replace	3060611-1	5-03229-200	12000					03/18/96	12000			8091
3075424	2ND Stage LP Turbine Blades Due Only At MPI See SB 72-5172; Marking Factor 900, Blade Limit 10	3075424							03/18/96				
* NOTE: 12/30/16 - 64 blades with 8 marks @ ETSN 6994.4													
3060671-2	Low Pressure Third Stage Turbine Rotor Disc Replace	3060671-2	5-03229-3957	12000					03/18/96	12000			8091
* NOTE: ASSEMBLY P/N 3060626-6													
3061823	3RD Stage LP Turbine Blades Rplc Due Only At MPI See SB 72-5172; Marking Factor 790, Blade Limit 10	3061823					6994.4	3832	12/30/16				
* NOTE: 12/30/16- INSTALLED 56 NEW BLADES @ 6994.4 TSN 3832 CSN													
3060180-1	Fan Drive Shaft Replace No Life Limit At This Time	3060180-1 TSN/TSO CSN/CSO	010339000686 2393.1 1651				4653.9	2543	08/30/07				
3074744-1	Tie Rod Replace No Life Limit At This Time	3074744-1 TSN/TSO CSN/CSO	4P-1709 8332.4 4341				6994.4	3832	12/30/16				

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
Green indicates the items baseline value used in next due calculation.
Imported from Customer's Tracking System for Forecasting Purposes.

ATA 72 Engine

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Date
	High Pressure Shouldered Shaft Replace <i>No Life Limit At This Time</i>	3060366-1	950740417672						03/18/96						
	High Pressure Turbine Forward Shaft Coupling Replace <i>No Life Limit At This Time</i>	3060502-2	950740418051						03/18/96						
	High Pressure Turbine Aft Shaft Coupling Replace <i>No Life Limit At This Time</i>	3060599-2	96074042685						03/18/96						
	Combustion Chamber Plenum Case Replace <i>No Life Limit At This Time</i>	3060534-3	5P17417						03/18/96						
	Low Pressure Turbine First Stage Nozzle Seal (A5) Replace <i>No Life Limit At This Time</i>	3073765-12	960740402159						03/18/96						
* NOTE: ASSEMBLY P/N 3060666-7															
	Low Pressure Turbine First Stage Nozzle Seal Support Replace <i>No Life Limit At This Time</i>	3060693-1	960740402136						03/18/96						
* NOTE: ASSEMBLY P/N 3060666-7															
	Turbine Interstage Transition Duct Replace <i>No Life Limit At This Time</i>	3060694-8 TSN/TSO CSN/CSO	00P13939 5420.2 3309						6994.4			3832			12/30/16
	Low Pressure Turbine First Stage Nozzle Assembly Replace <i>No Life Limit At This Time</i>	3060666-9 TSN/TSO CSN/CSO	07P05206 2470.0 828						6994.4			3832			12/30/16
	Accessory Gearbox Assembly Replace <i>No Life Limit At This Time</i>	3060827-2	S154												03/18/96
	Transfer Gearbox <i>No Life Limit At This Time</i>	3070093-16	P8139												03/18/96

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books
 Imported from Customer's Tracking System for Forecasting Purposes.

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.

PR-GJS
 Total Time: 7179.8
 Total Cycles: 3909

ATA 73 Engine Fuel and Control

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	Fuel Pump Replace	3060719-10	0135							03/18/96					
	No Life Limit At This Time														
	Fuel Control Assembly Replace	3070800-39	15191				4653.9	2543	08/31/07						
	No Life Limit At This Time	TSN/TSO	4558.2												

ATA 76 Engine Controls

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	DEEC (Digital Electronic Engine Control) Replace	2118882-4006	117-W0014				6477.4	3561	08/20/14						
	No Life Limit At This Time														

* NOTE: COMPONENT TSN/CSN UNK

ATA 79 Engine Oil

Code	Description	Part#	Serial#	Frequency			Last Compliance			Next Due			Remaining		
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Date	Hrs	Cyc	Mos
	Oil Lube Pump Replace	3060785-2	031405700597				2499.0	1239	12/30/03						
	No Life Limit At This Time	TSN/TSO	2204.6												

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7179.8
 Total Cycles: 3909



ENGINE Airworthiness Directives Status Tracker

Prepared for Nassau Editora, Radio E Televisao Ltda Current
 Reg#: PR-GJS Original Airworthiness Date: 03/18/1996
 Entered Into Service:
 Make: HONEYWELL Total Time: 7179.8
 Model: TFE731-40-1C Total Cycles: 3909
 Serial#: P-115111 Due Out: 03/09/2018
 Position: 3
 Biweekly #: 2019-1 Biweekly Date: 01/06/2019

Engine ADs		Revision/		Description		Compliance		Frequency		Last Compliance		Remaining		
Number	Date					Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
2008-02-19	03/06/2008	Prevent Uncontained Failure Of The HP Turbine Rotor Assembly	SB 72-3720/72-5185	NLT 100/4300/3300 CYCLES							11/13/2009			
* NOTE: NA														
2012-16-14	10/01/2012	2ND Stage Lpt2 Rotor Blades Failure	SB 72-5221	NLT 3000 HOURS, 5 YRS OR MPI							07/15/2013			
* NOTE: NA														
2014-12-52	07/28/2014	Prevent Lpt2 Blade Failure, Multiple Engine In-flight Shutdowns	SB 72-a3792, 72-a5242	PRIOR TO FLIGHT							08/20/2014			
* NOTE: NA SN														
2014-12-52E	06/10/2014	Prevent Lpt2 Blade Failure, Multiple Engine In-flight Shutdowns	Superseded	SUPERSEDED							07/28/2014			
2017-20-01	11/02/2017	To Prevent Uncontained Failure Of The Engine Fan Disk P/N 3060287-2	SB TFE731-72-5256	SEE AD							7179.8	3909	03/09/2018	
* NOTE: N/A - affected equipment not installed														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Printed on 1/11/2019
 11:3:26AM by ROTH



ENGINE Service Information Status

Prepared for Nassau Editora, Radio E Televisao Ltda
 Reg#: PR-GJS Original Airworthiness Date: 03/18/1996
 Entered Into Service:
 Make: HONEYWELL Total Time: 7179.8
 Model: TFE731-40-1C Total Cycles: 3909
 Serial#: P-115111 Due Out: 03/09/2018
 Position: 3

Tracker

Service Bulletins													
Number	Revision/ Date	Description	Compliance	Frequency			Last Compliance			Remaining			
				Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos	
72-5101	Rev:6 05/15/2007	Service Life Limits Of Critical Life Limited Components	RECOMMENDED							12/30/2016			
* NOTE: R6													
72-5107	Rev:INITIAL 09/13/1996	Replace Specified Identified (Part Number/Lot Number) Fuel And Oil Tubes	RECOMMENDED							12/30/2003			
* NOTE: NA													
72-5109	Rev:INITIAL 12/11/1996	Install Packings, PN S9413-036 And Seals, PN 3075506-2, On Tower Shaft Oil Transfer Tube	RECOMMENDED							08/30/2007			
* NOTE: PCW													
72-5110	Rev:INITIAL 12/04/1997	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED										
72-5110	Rev:1 03/28/2007	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED										
72-5110	Rev:2 02/12/2009	Replace Fan Support Shaft #1 Bellows Seal And Associated Components	RECOMMENDED										
72-5111	Rev:2 04/09/2001	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED							08/30/2007			
* NOTE: R2 PCW													
72-5111	Rev:3 03/28/2007	Replace Mainshaft No 4 And 5 Bellows Seals And Associated Vent/Oil System Components	RECOMMENDED										

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Printed on 1/11/2019
 11:3:26AM by ROTH

Service Bulletins

Number	Revision/		Description	Compliance			Frequency			Last Compliance			Remaining			
	Date			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Date	Hrs	Cyc	Mos	Hrs	Cyc	Mos
72-5112	Rev:INITIAL 03/06/1998		Bank Engine Model Conversions	OPTIONAL												
72-5112	Rev:1 09/20/1999		Bank Engine Model Conversions	OPTIONAL												
72-5112	Rev:2 09/15/2006		Bank Engine Model Conversions	OPTIONAL												
72-5112	Rev:3 06/07/2007		Bank Engine Model Conversions	OPTIONAL												
72-5115	Rev:1 04/03/2007		Replace Bolts That Secure The LP Compressor Case Assembly To The Combustion Chamber (Plenum) Case	RECOMMENDED									08/30/2007			
* NOTE: PCW R1																
72-5117	Rev:1 03/04/1998		Install/Rework Accessory Drive Gearbox Assembly With An Air-Oil Separator (Five Piece)(Inactive For Further Accomplishment)	INACTIVE												08/30/2007
* NOTE: R1 NA																
72-5117	Rev:2 05/01/1998		Install/Rework Accessory Drive Gearbox Assembly With An Air-Oil Separator (Five Piece)(Inactive For Further Accomplishment)	INACTIVE												
72-5120	Rev:1 03/28/2007		Replace The No. 4 High Pressure Rotor Roller Bearing	RECOMMENDED												08/30/2007
* NOTE: PCW R1																
72-5122	Rev:INITIAL 03/11/1998		Replacement Of Combustion Chamber On Specific Engines	RECOMMENDED												08/30/2007
* NOTE: PCW																
72-5124	Rev:INITIAL 03/18/1998		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED												
72-5124	Rev:1 07/02/1998		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED												
72-5124	Rev:2 01/22/2008		Install / Rework Accessory Drive Gearbox Assembly, PN 3060827-3 To PN 3060827-2	RECOMMENDED												

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books
 Imported from Customer's Tracking System for Forecasting Purposes.

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5126	Rev:1 06/27/2003	Inspect/Rework/Install Oil Filter Cover, PN 3072231-2/-3 To PN 3072231-5			OPTIONAL					08/30/2007				
* NOTE: R1 PCW														
72-5126	Rev:2 02/13/2008	Inspect/Rework/Install Oil Filter Cover, PN 3072231-2/-3 To PN 3072231-5			OPTIONAL									
72-5127	Rev:1 01/23/2002	Servicing With Mobil 254 Oil (Inactive For Further Accomplishment)			INACTIVE					08/30/2007				
* NOTE: NA R1														
72-5131	Rev:INITIAL 09/30/1999	Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, PN 3074108-2			RECOMMENDED									
72-5131	Rev:1 11/01/2007	Replace Specific Identified LP Turbine 2nd Stage Rotating Air Seal, PN 3074108-2			RECOMMENDED					08/30/2007				
* NOTE: NA														
72-5132	Rev:INITIAL 08/10/1999	Install (Oil) Filter Element PN 3070945-1 (Sampling Kit, PN 831044-1)			RECOMMENDED					08/30/2007				
* NOTE: R0 PCW 10/12/1999														
72-5132	Rev:1 02/12/2008	Install (Oil) Filter Element PN 3070945-1 (Sampling Kit, PN 831044-1)			RECOMMENDED									
72-5134	Rev:INITIAL 06/08/2000	Rework / Replace Fan Rotor Assembly			OPTIONAL									
72-5134	Rev:1 03/14/2003	Rework / Replace Fan Rotor Assembly			OPTIONAL									
72-5134	Rev:2 02/13/2008	Rework / Replace Fan Rotor Assembly			OPTIONAL									
72-5136	Rev:INITIAL 10/07/1999	Install Fan Stator Vane(s), PN 3060378-1/3060379-1 (As Applicable), And Associated Shroud Grommet(s) Or Replace The Fan Stator Vane Assembly			OPTIONAL									
72-5136	Rev:1 02/05/2008	Install Fan Stator Vane(s), PN 3060378-1/3060379-1 (As Applicable), And Associated Shroud Grommet(s) Or Replace The Fan Stator Vane Assembly			OPTIONAL									

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.

Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.

Green indicates the items baseline value used in next due calculation.

Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS

Total Time: 7179.8

Total Cycles: 3909

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			PN	RECOMMENDED	OPTIONAL	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5137	Rev:INITIAL 08/08/2001	Install High Pressure (HP) Turbine Rotor Assembly, PN 3060555-4	PN 3060555-4	RECOMMENDED						08/30/2007				
* NOTE: R0														
72-5137	Rev:1 12/14/2007	Install High Pressure (HP) Turbine Rotor Assembly, PN 3060555-4	PN 3060555-4	RECOMMENDED										
72-5138	Rev:1 12/14/2007	Installation Of Turbine Interstage Transition (ITT) Duct And Engine Clevis		OPTIONAL										
72-5138	Rev:INITIAL 01/22/2001	Installation Of Turbine Interstage Transition (ITT) Duct And Engine Clevis		OPTIONAL										
72-5140	Rev:INITIAL 08/27/2000	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL										
72-5140	Rev:1 09/20/2004	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL										
72-5140	Rev:2 02/24/2009	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL										
72-5140	Rev:3 05/11/2009	Rework / Install Low Pressure Second Stage Turbine (LPT2) Rotor Assembly Incorporating LPT2 Blades, PN 3075424-2, -3		OPTIONAL										
72-5141	Rev:2 06/11/2007	Inspection/Replacement (As Required) Of Threaded Ends Tie Rod (Low Pressure (LP) Tie Rod), Part Number 3074744-1		RECOMMENDED						08/30/2007				
* NOTE: R2 PCW 12/30/2003														
72-5142	Rev:INITIAL 07/13/2001	Installation Of HP Turbine Nozzle Segments, PN 3060840-1/-2/-3		RECOMMENDED										
72-5142	Rev:1 06/07/2007	Installation Of HP Turbine Nozzle Segments, PN 3060840-1/-2/-3		RECOMMENDED						08/30/2007				
* NOTE: R1														
72-5144	Rev:1 06/11/2007	Install Water Wash Tube Assembly, PN 3061180-1		RECOMMENDED						08/30/2007				
* NOTE: R1 PCW 12/30/2003														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5145	Rev:INITIAL 03/01/2001	Consumables Installation Kits	INFORMATIONAL											
72-5145	Rev:1 05/09/2003	Consumables Installation Kits	INFORMATIONAL											
72-5145	Rev:2 03/28/2007	Consumables Installation Kits	INFORMATIONAL											
72-5147	Rev:4 03/28/2007	Replace #4 And #5 Segmented Carbon Seals And Associated Vent/ Oil System Components	RECOMMENDED							08/30/2007				
* NOTE: R4 PCW 12/30/2003														
72-5147	Rev:5 01/28/2009	Replace #4 And #5 Segmented Carbon Seals And Associated Vent/ Oil System Components	RECOMMENDED											
72-5148	Rev:INITIAL 03/23/2001	Provide Authority For Installation Of An Alternate Transfer Gearbox Housing Assembly	OPTIONAL											
72-5148	Rev:1 12/14/2007	Provide Authority For Installation Of An Alternate Transfer Gearbox Housing Assembly	OPTIONAL											
72-5150	Rev:3 06/11/2007	Replace The Hoisting Bracket On The Fan Duct Set, PN 3072420-13 (Upper Half), On Specific Identified Engines	RECOMMENDED							08/30/2007				
* NOTE: NA R3														
72-5151	Rev:INITIAL 11/09/2001	Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer	RECOMMENDED							08/30/2007				
* NOTE: R0 NA														
72-5151	Rev:1 10/31/2007	Replace LP Turbine 2nd Stage (LPT2) Nozzle Retainer	RECOMMENDED											
72-5152	Rev:1 04/29/2002	Replace Outer Transition Liner, PN 3060573-1, With Part Number 3060573-2 Or 3067016-1	RECOMMENDED							08/30/2007				
* NOTE: R1 PCW 12/30/2003														
72-5152	Rev:2 08/17/2007	Replace Outer Transition Liner, PN 3060573-1, With Part Number 3060573-2 Or 3067016-1	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5153	Rev:INITIAL 01/23/2007	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											
72-5153	Rev:1 05/28/2015	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											
72-5153	Rev:2 04/22/2018	Install Fan Duct Set, PN 3072420-13 (Matched Set), Or Upper By-pass Duct, PN 3061300-3, -5, -7 Or PN 70060073-1 (As Applicable), And Lower By-pass Duct, PN 3061300-4, -6, -8 Or PN 70060074-1 (As Applicable)	INFORMATIONAL											
72-5154	Rev:1 09/27/2002	Inspection Of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1	RECOMMENDED							08/30/2007				
* NOTE: R1														
72-5154	Rev:2 11/01/2007	Inspection Of LP 3rd Stage Turbine (LPT3) Blade, Part Number 3060690-1 <i>Recurring upon access</i>	RECOMMENDED											
72-5156	Rev:INITIAL 05/20/2003	Repositioning Of Branched Engine Harness Assembly	OPTIONAL											
72-5156	Rev:1 09/30/2005	Repositioning Of Branched Engine Harness Assembly	OPTIONAL											
72-5157	Rev:INITIAL 03/07/2003	Remove Specific Identified LP Compressor Second Stage (LPC2) Discs	RECOMMENDED							08/30/2007				
* NOTE: R0 NA														
72-5157	Rev:1 11/01/2007	Remove Specific Identified LP Compressor Second Stage (LPC2) Discs	RECOMMENDED											
72-5158	Rev:2 02/18/2005	Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention	RECOMMENDED							08/30/2007				
* NOTE: R2														
72-5158	Rev:3 03/11/2009	Install An Improved Fan Disc, Fan Shaft, And Fan Roller Bearing To Enhance Fan Balance Retention	RECOMMENDED											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7179.8
 Total Cycles: 3909

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			PN	RECOMMENDED	OPTIONAL	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5159	Rev:2 05/28/2004	Install The Improved Filter By-Pass Valve Assembly	PN 3060782-2	RECOMMENDED						08/30/2007				
* NOTE: R2 PCW 06/13/2003														
72-5159	Rev:3 10/26/2007	Install The Improved Filter By-Pass Valve Assembly	PN 3060782-2	RECOMMENDED										
72-5159	Rev:4 09/20/2012	Install The Improved Filter By-Pass Valve Assembly	PN 3060782-2	RECOMMENDED										
72-5160	Rev:INITIAL 06/05/2003	Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, PN 3060788-1		OPTIONAL										
72-5160	Rev:1 01/21/2008	Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating LPT3 Blades, PN 3060788-1		OPTIONAL										
72-5162	Rev:INITIAL 02/14/2003	Replacement Of The Front Frame Assembly		OPTIONAL										
72-5163	Rev:INITIAL 03/14/2003	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5163	Rev:1 02/17/2004	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5163	Rev:2 06/14/2005	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5163	Rev:3 07/03/2008	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5163	Rev:4 11/16/2015	Provide Eddy Current Inspection Instructions For The Fan Disc Dovetail Slots		RECOMMENDED										
72-5164	Rev:INITIAL 05/07/2004	Replace The Number 6 Rear Bearing Housing		OPTIONAL										
72-5164	Rev:1 12/14/2007	Replace The Number 6 Rear Bearing Housing		OPTIONAL										
72-5165	Rev:INITIAL 09/10/2003	Install An Improved LP Turbine 2ND (LPT2) Stage Nozzle Retainer And LPT2 Stage Shroud Segments		RECOMMENDED						08/30/2007				
* NOTE: R0 PCW 12/30/2003														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5165	Rev:1 08/17/2007	Install An Improved LP Turbine 2ND (LPT2) Stage Nozzle Retainer And LPT2 Stage Shroud Segments	RECOMMENDED											
72-5166	Rev:1 07/21/2004	Replace Specific Identified High Pressure Turbine (HPT) Tie Shaft Plain Round Nuts, PN 3070151-4	RECOMMENDED							08/30/2007				
* NOTE: NA R1														
72-5172	Rev:5 08/07/2015	HPT And LPT Blade Hour Tracking And Recommended Blade Replacement Intervals For TFE731-20, -40, -50, -60 Series Engine Models	RECOMMENDED							12/30/2016				
* NOTE: R5														
72-5173	Rev:INITIAL 06/15/2005	Replace Specific Identified Helical Ring Gears, PN 3060277-2, And Inspect Associated Parts	RECOMMENDED											
72-5173	Rev:1 11/14/2005	Replace Specific Identified Helical Ring Gears, PN 3060277-2, And Inspect Associated Parts	RECOMMENDED							08/30/2007				
72-5174	Rev:INITIAL 03/05/2004	Remove Specific Identified High Pressure Turbine (HPT) Rotor Discs	RECOMMENDED							08/30/2007				
* NOTE: R0 NA														
72-5174	Rev:1 12/04/2007	Remove Specific Identified High Pressure Turbine (HPT) Rotor Discs	RECOMMENDED											
72-5175	Rev:INITIAL 09/08/2004	Replace Low Pressure (LP) 3rd Stage Turbine (LPT3) Blades, PN 3060690-1, On Specific Identified LPT3 Rotor Assemblies	RECOMMENDED							08/30/2007				
* NOTE: NA														
72-5176	Rev:INITIAL 05/12/2004	Accessory Drives Section - Install Air-Oil Separator, Part No. 3075781-1 <i>Accomplishment of 72-5124 will no longer be applicable when the equipment has been modified in accordance with the accomplishment instructions outlined in this service bulletin</i>	RECOMMENDED							08/30/2007				
* NOTE: R0														
72-5177	Rev:INITIAL 08/10/2004	Replace Specific Identified LP Second Stage Turbine Blades (LPT2), PN 3075424-1/-2 (As Applicable)	RECOMMENDED							08/30/2007				
* NOTE: NA														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining						
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos				
72-5178	Rev:INITIAL 10/28/2008	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2																
72-5178	Rev:1 05/11/2009	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2																
72-5178	Rev:2 08/04/2014	Install Low Pressure First Stage Turbine (LPT1) Blades, PN 3060612-2																
72-5179	Rev:INITIAL 02/16/2009	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3																
72-5179	Rev:1 05/11/2009	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3																
72-5179	Rev:2 07/03/2014	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3																
72-5179	Rev:3 08/04/2014	Install Low Pressure Second Stage Turbine (LPT2) Blades, PN 3075424-3																
72-5181	Rev:INITIAL 06/17/2005	Rework / Install Planetary Gearshaft Assembly, PN 3060129-3, -4 To PN 3060129-7																08/30/2007
* NOTE: R0																		
72-5181	Rev:1 07/03/2008	Rework / Install Planetary Gearshaft Assembly, PN 3060129-3, -4 To PN 3060129-7																
72-5191	Rev:INITIAL 03/28/2007	Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly PN 3072416-15/-16																
72-5191	Rev:1 02/06/2008	Install Low Pressure Second Stage Compressor (LPC2) Rotor Assembly PN 3072416-15/-16																
72-5194	Rev:3 10/19/2012	Install Improved Design HP And LP Turbine Shrouds And Associated Hardware																12/30/2016
* NOTE: R3																		
72-5195	Rev:INITIAL 07/16/2007	Install Low Pressure Compressor (LPC) Case Assembly PN 3074730-5																
72-5195	Rev:1 09/19/2008	Install Low Pressure Compressor (LPC) Case Assembly PN 3074730-5																

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining						
			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos				
72-5196	Rev:INITIAL 04/29/2008	Replace / Rework Fan Stator Vane Assembly, PN 3060163-4 To PN 3060163-5 And PN 3060239-4 To PN 3060239-5 (As Applicable)				OPTIONAL												
72-5196	Rev:1 11/18/2008	Replace / Rework Fan Stator Vane Assembly, PN 3060163-4 To PN 3060163-5 And PN 3060239-4 To PN 3060239-5 (As Applicable)				OPTIONAL												
72-5197	Rev:INITIAL 09/17/2007	Install Deswirl PN 3060326-4				RECOMMENDED												
72-5197	Rev:1 12/19/2008	Install Deswirl PN 3060326-4				RECOMMENDED												
72-5198	Rev:INITIAL 09/07/2007	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5				RECOMMENDED												
72-5198	Rev:1 03/14/2008	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5				RECOMMENDED												
72-5198	Rev:2 09/19/2008	Inspect Low Pressure Compressor First Stage Rotor Assembly (LPC1) Blades, And Rework LPC2 Rotating Shroud, PN 3072403-4 To PN 3072403-5				RECOMMENDED												
72-5199	Rev:INITIAL 01/18/2008	Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 And LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)				RECOMMENDED												
72-5199	Rev:1 09/19/2008	Install Improved-Design First Stage Low Pressure Compressor (LPC1) Rotor Shroud, PN 3071873-6 And LPC1 Rotor Assembly, PN 3070440-24, -26 (As Applicable)				RECOMMENDED												
72-5200	Rev:INITIAL 05/22/2008	Replace LP Compressor 2ND Stage Rotor Assembly, PN 3072416 With PN 3075841 <i>When LPC2 rotor disc is scrapped</i>				OPTIONAL												
72-5201	Rev:INITIAL 12/10/2008	Replace Low Pressure Compressor 4th Stage (LPC4) Case and Vane Assembly, PN 3060361-4 With PN 3060361-5				RECOMMENDED												
72-5202	Rev:INITIAL 04/21/2008	Install Improved No. 4 Segmented Carbon Seal, PN 3060437-1, And No. 5 Segmented Carbon Seal, PN 3060436-1				RECOMMENDED												

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/		Description	Compliance			Frequency			Last Compliance			Remaining		
	Date			Hrs	Cyc	Mos	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5203	Rev:INITIAL 04/21/2008		Install Improved No. 1 Carbon Seal, PN 3060457-1	RECOMMENDED							12/30/2016				
72-5204	Rev:1 05/11/2009		Incorporate Improved Design Low Pressure Turbine First Stage (LPT1) Rotor Assembly And LPT2 Rotor Assembly Blade Retainers	RECOMMENDED							12/30/2016				
* NOTE: R1															
72-5208	Rev:INITIAL 10/23/2009		Rework / Install LP Third Stage Turbine (LPT3) Rotor Assembly Incorporating Improved Design LPT3 Blades PN 3061823-2	RECOMMENDED							12/30/2016				
72-5215	Rev:INITIAL 03/18/2010		Install Improved Rear Bearing Housing Support That Provides Additional Clearance To LPT3 Blades <i>Only if contact (rub) has occurred</i>	OPTIONAL											
72-5216	Rev:1 10/28/2011		Install Improved Plain Encased Seal, PN 3020052-26	RECOMMENDED							12/30/2016				
* NOTE: R1															
72-5217	Rev:INITIAL 10/22/2010		Install Improved Front Frame Assembly, PN 3060421-3, PN 3061505-4, Or PN 3060439-2 <i>When the front frame assembly is replaced for cause.</i>	OPTIONAL											
72-5218	Rev:INITIAL 11/08/2010		Introduction Of New Second Stage Low Pressure Compressor Blade (LPC2), PN 3075840-3	OPTIONAL											
72-5221	Rev:INITIAL 11/11/2010		Replace Specific Low Pressure 2nd Stage Turbine Rotor Blades, PN 3075424-2, -3	RECOMMENDED							01/09/2013				
* NOTE: NA															
72-5221	Rev:1 11/02/2017		Replace Specific Low Pressure 2nd Stage Turbine Rotor Blades, PN 3075424-2, -3	RECOMMENDED											
72-5222	Rev:INITIAL 08/19/2011		Install Front Frame Assembly That Has Additional Corrosion Protection Features	RECOMMENDED											
72-5222	Rev:1 05/01/2012		Install Front Frame Assembly That Has Additional Corrosion Protection Features	RECOMMENDED											
72-5223	Rev:INITIAL 08/19/2011		Apply Protective Coating To The Aft Flange Of The Composite Bypass Duct	RECOMMENDED							12/30/2016				
* NOTE: NA BY DUCT P/N															

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

PR-GJS
 Total Time: 7179.8
 Total Cycles: 3909

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5223	Rev:1 04/20/2018	Apply Protective Coating To The Aft Flange Of The Composite Bypass Duct on TFE731-20, -40, -50, and -60 Engine Models	RECOMMENDED											
72-5224	Rev:INITIAL 08/19/2011	Inspect, Rework, Or Replace Composite Bypass Ducts	RECOMMENDED											
72-5224	Rev:1 04/19/2018	Inspect, Rework, Or Replace Composite Bypass Ducts On TFE731-20, -40, -50, and -60 Engine Models.	RECOMMENDED											
72-5225	Rev:INITIAL 07/22/2011	Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, PN 3072403-6	RECOMMENDED											
72-5225	Rev:1 08/17/2012	Install Improved Low Pressure Compressor Second Stage (LPC2) Shroud, PN 3072403-6	RECOMMENDED											
72-5227	Rev:INITIAL 03/19/2014	Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals	RECOMMENDED											
72-5227	Rev:1 07/24/2015	Introduction Of Accessory Drive Gearbox Assembly With Hydrodynamic Carbon Face Seals	RECOMMENDED											
72-5236	Rev:INITIAL 11/25/2013	Installation Of New Or Reworked Fan Inlet Housing	RECOMMENDED											
72-5236	Rev:1 01/23/2015	Installation Of New Or Reworked Fan Inlet Housing <i>When the fan inlet housing is no longer serviceable.</i>	OPTIONAL											
72-5247	Rev:INITIAL 07/08/2015	Replace Fan Stator Vane Assembly, PN 3060163-3, -4, -5 With PN 70060130-1	RECOMMENDED											
72-5251	Rev:INITIAL 03/25/2015	Accomplish Eddy Current Inspection Of Specific Second Stage Low Pressure Turbine (LPT2) Blades PN 3075424	RECOMMENDED											
72-5253	Rev:INITIAL 12/02/2015	Improved Third Stage Low Pressure Compressor (LPC3) Rotating Shroud, PN 3072404-5	RECOMMENDED											
72-5256	Rev:INITIAL 10/07/2016	Identify and Replace Specific Fan Discs, PN 3060287-2, with Suspect Shot Peened Rolled Edges	RECOMMENDED										12/30/2016	

* NOTE: NA BY DISC P/N

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
72-5264	Rev:INITIAL 06/08/2016	Replace Rigid Shaft Coupling, PN 3060116-1 With PN 3060116-2, On TFE731-20, -40 Engines <i>Requires Honeywell engineering authorization for incorporation.</i>	RECOMMENDED											
72-5267	Rev:INITIAL 04/22/2018	Composite Bypass Duct Optional Replacement Configurations On Specific TFE731-20, -40 Engine Models	OPTIONAL											
73-5106	Rev:INITIAL 11/05/1996	Replace Fuel Flow Meter To Flow Divider Assembly, PN 3061176-1, With PN 3061199-1	PN RECOMMENDED							08/30/2007				
* NOTE: PCW														
73-5107	Rev:INITIAL 06/29/1999	One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, PN 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly	RECOMMENDED							08/30/2007				
* NOTE: RO NA														
73-5107	Rev:1 11/16/2007	One Time Inspection For Specific Identified Fuel Control Compressor Discharge Sensor Bellows, PN 3074139-2, And Replacement (As Required) Of The Metering Valve Assembly	RECOMMENDED											
73-5108	Rev:INITIAL 05/23/1997	Replace Fuel Pump, PN 3060719-10 With PN 3060760-1	OPTIONAL											
73-5115	Rev:1 12/07/1998	Rework Fuel Pump Using Differential Pressure Indicator, PN 5911442-2	RECOMMENDED							08/30/2007				
* NOTE: R1 PCW 10/12/1999														
73-5115	Rev:2 01/25/2008	Rework Fuel Pump Using Differential Pressure Indicator, PN 5911442-2	RECOMMENDED											
73-5116	Rev:INITIAL 05/15/2000	Install Combustor to 6 O'Clock Strut Tube Assembly, PN 3061264-1	RECOMMENDED							08/30/2007				
* NOTE: RO PCW 12/30/2003														
73-5116	Rev:1 01/25/2008	Install Combustor to 6 O'Clock Strut Tube Assembly, PN 3061264-1	RECOMMENDED											
73-5117	Rev:1 05/25/2001	Install Fuel Pump To Fuel Heat / Oil Cooler Tube Assembly, PN 3061286-1	RECOMMENDED							08/30/2007				
* NOTE: PCW R1														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos		
73-5118	Rev:2 03/09/1999	Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motor	RECOMMENDED								08/30/2007			
* NOTE: R2 NA														
73-5118	Rev:3 06/11/2007	Replace Specific Identified Fuel Control Assemblies Having Suspect Torque Motor	RECOMMENDED											
73-5120	Rev:INITIAL 02/11/2000	Install Fuel Manifold Flexible Hose Assemblies (Primary), PN 3061294-1	RECOMMENDED								04/13/2001			
73-5121	Rev:INITIAL 12/17/1999	Rework / Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2	RECOMMENDED								08/30/2007			
* NOTE: R0 PCW 04/13/2001														
73-5121	Rev:1 02/22/2008	Rework / Replace Fuel Nozzle Assembly, PN 3060540-3, With PN 3060540-2	RECOMMENDED											
73-5124	Rev:INITIAL 05/25/2001	Install Clamps Between Fuel Heater Pump To Fuel Heater / Oil Cooler Tube Assembly And The Fuel Heater / Oil Cooler To Fuel Pump Tube Assembly	RECOMMENDED								08/13/2001			
* NOTE: R0														
73-5124	Rev:1 02/08/2008	Install Clamps Between Fuel Heater Pump To Fuel Heater / Oil Cooler Tube Assembly And The Fuel Heater / Oil Cooler To Fuel Pump Tube Assembly	RECOMMENDED											
73-5128	Rev:INITIAL 12/21/2001	Install Primary Fuel Tube Assembly, PN 3061203-1, And Secondary Fuel Tube Assembly, PN 3061204-1	RECOMMENDED								08/30/2007			
* NOTE: R0 PCW 12/30/2003														
73-5128	Rev:1 12/12/2007	Install Primary Fuel Tube Assembly, PN 3061203-1, And Secondary Fuel Tube Assembly, PN 3061204-1	RECOMMENDED											
73-5130	Rev:INITIAL 10/07/2002	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED								08/30/2007			
* NOTE: R0 NA														
73-5130	Rev:1 06/18/2007	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED											
73-5131	Rev:INITIAL 05/28/2004	Install Fuel Pump That Incorporates Differential Pressure Indicator, PN 5913809-2	OPTIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			OPTIONAL	RECOMMENDED	RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
73-5131	Rev:1 11/14/2005	Install Fuel Pump That Incorporates Differential Pressure Indicator, PN 5913809-2	OPTIONAL											
73-5135	Rev:INITIAL 03/29/2005	Replace Specific Identified Main Turbine Engine Fuel Controls With A Suspect Overspeed Governor Assembly Installed	RECOMMENDED							08/30/2007				
* NOTE: NA														
73-5136	Rev:INITIAL 09/12/2005	Replace Main Turbine Engine Fuel Pump Fuel Filter Element With Fuel Filter Element, PN 897830-1	RECOMMENDED							12/30/2016				
73-5137	Rev:INITIAL 03/15/2006	Replace Specific Identified Main Turbine Engine Fuel Pumps (Fuel Pump), PN 3060760-4	RECOMMENDED							08/30/2007				
* NOTE: NA														
73-5138	Rev:INITIAL 03/21/2006	Replace Specific Identified Fuel Control Assemblies Having A Suspect Overspeed And / Or Manual Mode Solenoid Valve Installed	RECOMMENDED							08/30/2007				
* NOTE: NA														
73-5140	Rev:INITIAL 05/31/2013	Install Motive Flow Fuel Pump, PN 70060003-1	OPTIONAL											
73-5141	Rev:INITIAL 03/28/2012	Install Improved Main Turbine Engine Fuel Control Assembly, PN 3070800-47 and -49	RECOMMENDED											
73-5141	Rev:1 06/21/2012	Install Improved Main Turbine Engine Fuel Control Assembly, PN 3070800-47 and -49 <i>When the main turbine engine fuel control assembly is replaced for cause.</i>	OPTIONAL											
73-5146	Rev:INITIAL 05/04/2017	Install Improved Fuel Control Assembly (FCA), P/N 3070800-28, -30, -37, -47, -69, And -79, With Improved Solenoid Attachment Screws On TFE731-20, -40, -50, And -60 Engine Models	RECOMMENDED											
73-5146	Rev:1 01/24/2018	Install Improved Fuel Control Assembly (FCA), P/N 3070800-28, -30, -37, -47, -69, And -79, With Improved Solenoid Attachment Screws On TFE731-20, -40, -50, And -60 Engine Models	RECOMMENDED											
75-5101	Rev:INITIAL 11/12/2003	Install Low Pressure (LP) Bleed Duct, PN 3060770-2 Or 3060770-3, And Outer Flange, PN 3071244-2 (As Applicable)	OPTIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			(DEEC) PN	OPTIONAL	RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
76-5107	Rev:INITIAL 12/24/1997	Install Digital Electronic Engine Control (DEEC) PN 2118882-4003		OPTIONAL						08/30/2007				
* NOTE: PCW														
76-5109	Rev:2 09/20/2004	Install / Rework Solenoid Controller Valve, PN 109696-5-1 To PN 109696-6-1		OPTIONAL						08/30/2007				
* NOTE: PCW R2														
76-5110	Rev:INITIAL 06/17/1998	Install Digital Electronic Engine Control (DEEC) PN 2118882-4004		RECOMMENDED						08/30/2007				
* NOTE: PCW														
76-5112	Rev:INITIAL 09/15/1999	Install Digital Electronic Engine Control (DEEC) PN 2118882-4005		RECOMMENDED						08/30/2007				
* NOTE: PCW														
76-5115	Rev:INITIAL 10/25/2001	Install Digital Electronic Engine Control (DEEC) PN 2118882-4006		RECOMMENDED										
76-5115	Rev:1 06/18/2002	Install Digital Electronic Engine Control (DEEC) PN 2118882-4006		RECOMMENDED						12/30/2003				
* NOTE: R1														
76-5116	Rev:INITIAL 10/28/2002	Rework / Install Surge Bleed Valve, PN 978812-7-1		OPTIONAL										
76-5116	Rev:1 01/30/2008	Rework / Install Surge Bleed Valve, PN 978812-7-1		OPTIONAL										
77-5105	Rev:2 02/04/2000	Install Improved Thermocouple Harness		RECOMMENDED						08/30/2007				
* NOTE: PCW R2														
77-5108	Rev:2 03/06/2006	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security		RECOMMENDED						08/30/2007				
* NOTE: R2														
77-5108	Rev:3 08/11/2008	Install Shrink Wrap Over Electrical Connector On The Speed (N1 Monopole) Sensor And Attaching N1 Lead Assembly For Security		RECOMMENDED										

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			Optional	Required	Recommended	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
77-5109	Rev:INITIAL 08/18/2008	Install Improved N1 Lead Assembly, PN 3060718-4 Or PN 3060729-4 <i>When N1 lead assembly is replaced for cause.</i>	OPTIONAL											
79-5104	Rev:2 09/20/2004	Replace Oil Flow Reduction Valve (ORV)	OPTIONAL							08/30/2007				
* NOTE: R2 PCW														
79-5105	Rev:1 03/28/2007	Oil Lube Pump, PN 3060701-4/-5 To PN 3060701-6	RECOMMENDED							08/30/2007				
* NOTE: R1 PCW														
79-5106	Rev:5 12/11/2002	Install An Improved Oil Drainback System	RECOMMENDED							08/30/2007				
* NOTE: R5 PCW 10/12/1999														
79-5106	Rev:6 03/12/2008	Install An Improved Oil Drainback System	RECOMMENDED											
79-5106	Rev:7 02/06/2013	Install An Improved Oil Drainback System	RECOMMENDED											
79-5107	Rev:INITIAL 04/10/2007	Install Loop Clamps On Oil Tubes To Prevent Vibration And Chaffing	RECOMMENDED											
79-5110	Rev:INITIAL 02/28/2001	Replace / Rework Oil Tank Filler Plug For Use With Lockwire	OPTIONAL											
79-5110	Rev:1 03/12/2008	Replace / Rework Oil Tank Filler Plug For Use With Lockwire	OPTIONAL											
79-5110	Rev:2 05/09/2018	Replace / Rework Oil Tank Filler Plug For Use With Lockwire On TFE731-20, -40, -50, -60 Model Engines	OPTIONAL											
79-5111	Rev:1 03/28/2007	Install Oil Lube Pump, PN 3060701-7	RECOMMENDED							08/30/2007				
* NOTE: NA R1														
79-5112	Rev:2 03/28/2007	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump), Part No's. 3060785-1/-2	RECOMMENDED							08/30/2007				
* NOTE: R2 PCW 12/30/2003														

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
			RECOMMENDED	RECOMMENDED	RECOMMENDED	Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
79-5112	Rev:3 04/12/2012	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump), Part No s. 3060785-1/-2	RECOMMENDED											
79-5113	Rev:1 03/28/2007	Install Oil Supply Tube Assembly, Part Number 3061207-6 Or 3061208-6	RECOMMENDED							08/30/2007				
* NOTE: PCWR1														
79-5114	Rev:INITIAL 11/12/2003	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5114	Rev:1 04/26/2004	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5114	Rev:2 03/12/2008	Install Fairing Panels, Part Number 3061265-1 And 3061289-1	OPTIONAL											
79-5115	Rev:INITIAL 03/12/2004	Replace Oil Tank Sight Glass Decal, PN 461-512-9001	OPTIONAL											
79-5116	Rev:INITIAL 01/05/2007	Replace Seal On By-Pass Duct Panel, PN 3061101-1/-2/-4/-5	OPTIONAL											
79-5117	Rev:INITIAL 09/10/2007	Replace The Seal(s) On Bottom Panel PN 3060947-2 Through -11	OPTIONAL							12/30/2016				
79-5118	Rev:INITIAL 06/18/2007	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5118	Rev:1 09/23/2008	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5118	Rev:2 02/06/2013	Install Oil Cooler Inlet Tube Assembly, PN 70060057-2	OPTIONAL											
79-5119	Rev:INITIAL 08/26/2009	Install Improved Packings In Oil Lube And Scavenge Pump, PN 3060785-1, -2 <i>Next access is defined as the removal of the oil pressure regulator</i>	OPTIONAL											
79-5121	Rev:INITIAL 02/29/2012	Install Lube With Regulator And Scavenge Pump (Oil Lube Pump) PN 3060785-3 <i>When replaced for cause.</i>	OPTIONAL											

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.

Service Bulletins

Number	Revision/ Date	Description	Compliance			Frequency			Last Compliance			Remaining		
						Hrs	Cyc	Mos	Hrs	Cyc	Date	Hrs	Cyc	Mos
79-5125	Rev:INITIAL 07/25/2013	Install New Forward No. 6 Bearing Oil Supply Tube Assembly, PN 3060900-2, And Mid No. 6 Bearing Oil Supply Tube Assembly, PN 3060901-6	RECOMMENDED											
79-5127	Rev:INITIAL 03/14/2014	Install Two-Piece Air-Oil Cooler Supply Tube Assembly	RECOMMENDED											
79-5129	Rev:INITIAL 05/09/2018	Install Improved Oil Tank Instruction Plate To Prevent Oil Tank Overservicing On TFE731-20, -40, -60 Model Engines	RECOMMENDED											
A72-5121	Rev:INITIAL 01/21/1998	One Time Oil And Filter Resample	RECOMMENDED							08/30/2007				
* NOTE: NA														
A72-5185	Rev:INITIAL 07/05/2006	Inspect / Replace Specific Identified High Pressure (HP) Turbine Rotor Disks, Part No. 3060841-1	ALERT							08/30/2007				
* NOTE: NA														
A72-5240	Rev:INITIAL 06/25/2014	Inspect Or Replace Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Engines affected by SB 72-A5242 only	ALERT							08/20/2014				
* NOTE: R0 NA DUE TO BLADES HAVE LESS THAN 250 HOURS TSN														
A72-5242	Rev:1 06/25/2014	Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades	ALERT							08/20/2014				
* NOTE: R1														
A72-5242	Rev:2 08/29/2014	Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades	ALERT											
A72-5246	Rev:INITIAL 06/25/2014	Eddy Current Inspect Second Stage Low Pressure Turbine Rotor Assemblies With Suspect Blades Engine affected by SB 72-A5240, 72-A5241	ALERT							08/20/2014				
* NOTE: R0 NA														
A73-5110	Rev:INITIAL 03/16/1998	Inspection Of Secondary Fuel Line Manifold For Chaffing/ Cutting	ALERT							03/18/1998				
A73-5114	Rev:INITIAL 07/30/1998	Inspect Fuel Pump To Fuel Heater / Oil Cooler Tube Assembly, PN 3061174-1, For Fretting (Chaffing)	ALERT							09/02/1998				

Data in this report is provided for planning purposes only and neither supplements nor replaces official log books

Red indicates the item is currently open/due.
 Blue indicates the item is due within 60 hours, 60 cycles, and/or 2 months.
 Green indicates the items baseline value used in next due calculation.
 Imported from Customer's Tracking System for Forecasting Purposes.