

**Aircraft Operator Information:**

**Name:** Itabira Agro Industrial S.A.  
Andar – Centro  
**City:** São Paulo

**Address:** Av. Prestes Maia 220 6º  
**State:** SP                      **Country:** Brazil

**Aircraft Information:**

**Aircraft type:** C208  
**Time:** 750,6 Hrs.\*

**Aircraft SN:** 20800372    **Aircraft Total**

\*Actual total time of the aircraft after a ferry flight from Manaus (SWFN) to Recife (SBRF).

**Describe Aircraft Damage (Include Photographs):**

During a normal landing of the Aircraft in Manaus (SWFN) the aircraft hit the ground 10 yards before the runway with it's right wheel (see picture below).



It was verified that during the hard landing the right landing gear was damaged.



**Accident/ Incident Information:**

**Location (City, State, Country):** Manaus, AM, Brazil

**Date:** February 15<sup>th</sup>, 2006      **Time:** 15:35 (Zulu)

**Engine Model:** PT6A-114A (PN:3044000) **Engine Serial N°:** PCE-PC1075

**Total Time Since New:** 739,1 Hours      **Total Cycles Since New:** 787 Starts

**Total Time Since O/H:** N/A      **Total Cycle Since O/H:** N/A















