

The Standard Aircraft Log SA-2

© 1991–2007 Aviation Supplies & Academics, Inc.

ASA-SA-2 ISBN 1-56027-117-5 978-1-56027-117-8

All rights reserved. Reproduction or use, without express permission, in any manner, is prohibited.

Published by Aviation Supplies & Academics, Inc. 7005 132nd Place SE Newcastle, WA 98059-3153 Website: www.asa2fly.com Email: asa@asa2fly.com

Printed in China





WIPLINE FLOAT MODEL: 3730A
SERIAL NUMBER (LEFT): 37/1/3
SERIAL NUMBER (RIGHT): 37114
DATE OF MANUFACTURE: 07/75
DATE OF INITIAL INSTALLATION: 07/19/2012

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alte Entries must be endorsed with Name, Rating and Certificate Nur Technician or Repair Facility. (<i>See</i> back pages for other specific	mber of		YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)	
	JULY 19, 2012 N 60755 TACH 750.9				-	i i	Februa hours s	ry 22, 2013 Tach since install and l	772 Perforast inspecti	m annual insp on.	Steven W. Seeley A&P 2236017 IA Core. U Jelly	
	CO CLI LH 001 LH GE/ CAI REF GE/ STC	COMPLETED ANNUAL/200 HR INSPECTION OF FLOATS PER WIPAIRE MM INSPECTION GUIDE. COMPLETED THE FOLLOWING REPAIRS. CW WIPAIRE SL 26 MAIN GEAR ROLL PIN. CLEANED AND TREATED OR REPLACED HARDWARE AND PLUMBING FITTINGS AS NEEDED IN LH AND RH FLOATS. REPLACED ALL LH AND RH BAGGAGE COMPARTMENT SEALS PN 3A08525-001. REPLACED LH AND RH NOSE WHEEL PIVOT BLOCK SPRINGS PN 3A06525-001. REPLACED LH AND RH NOSE GEAR EXTERNAL POSITION INDICATORS PN 3A06000-004. RESEALED NOSE GEAR BOXES TO BULKHEAD.REPLACED VARIOUS PULLY'S IN LH AND RH FLOAT PN MS20219-2. REMOVED AND RESEALED LH AND RH MAIN GEAR SHOCK STRUTS. RESEALED ALL BRAKE CALIPERS, O RING PN MS28775-218.REPAIRED WIRING THROUGHOUT FLOATS AS NEEDED. REPLACED LH NOSE FORK ANTI ROTATION PIN. REINSTALLED WIPAIRE REPAIRED LANDING GEAR SELECTOR. INSTALLED SERVICEABLE WIPAIRE 3730A FLOATS SN 37113 AND 37114 IAW STC SA18GL DATED 4/8/91 AND INSTALLATION DRAWING 3R1-121 REV B DATED 2/22/77. COMPLETED ALL FUNCTIONAL AND INDICATOR CHECKS. BLED BRAKES AND SERVICED					August 30, 2013 Tach 781 Installed new Michelin tires and tubes on retractable floats new bearings and seals all main 4 forward wheels not changed at this time. Steven W. Seeley A&P 2236012 March 8, 2014 Tach 782 Perform annual inspection on floats per FAR 43 appendix D and approve for return to service. 31 since install and last inspection. Steven W. Seeley A&P 2236012 IA					
	THE IDEI CUR APP FILE W/O SIGN	E AIRCRAINTIFIED A RRENT REC ROVED FO E AT THIS R NO. 73982 NED	T AIRFRAM BOVE WAS GULATIONS O R RETURN TO EPAIR STATIC	E, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE REPAIRED AND INSPECTED IN ACCORDANCE WITH IF THE FEDERAL AVIATION ADMINISTRATION AND IS SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON		The control of the co						
•					To Associate to the State of th		Alleren Sellierungeras i					

ų.