

WIPLINE FLOAT MODEL:	3450A	_
	PT TYCHER	
	Steppinstandon film date	
SERIAL NUMBER (LEFT):	34069	_
1 32 TO 15 T		
SERIAL NUMBER (RIGHT):	34070	
/r- surrengly, tracketted:		
DATE OF MANUFACTURE:	7-01	
Sirial		
Disc. Bricket	Sector -	niśw
DATE OF INITIAL INSTALLAT		let li

Unite I

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Certifica Technician or Repair Facility. (See back pages for other specific and the second	Ite Number
DATE	INSTALI CESSNA WIPAIRI THE AI IDENTIF CURREN APPROV THIS REI W/O NO.	LED WIPL MODEL E, INC., ST RCRAFT IED ABO IT REGUL ED FOR R PAIR STAT	INE MODEL T206H, SE C# SA011850 AIRFRAME, VE WAS R	AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE REPAIRED AND INSPECTED IN ACCORDANCE WITH THE FEDERAL AVIATION ADMINISTRATION AND IS SERVICE. PERTINENT OF THE REPAIR ARE ON FILE AT DATE 7-18-2001	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2001 DATE	1,000			roommonarror mopair raomy. (See Saint pages to saint p
10/3	72.1			Completed annual inspection this date.
				Completed annual inspection this date. Tightened reservoir sight slass as
				required.
				Come Diehoff for
				Wicking Inc. CR\$ RJUR390K
12/14	102.5			Removed flocks and installed wheels.
1941				(seasonal change).
1				James Wiehoff for
				Widerenc. CRD # CRJUR390K
5/1/02	116.5	r		Removed wheels and installed floats.
11				(seasonal change)
				Sames Wiehold for
				Woodre Inc. CRS RJWR390K

.

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entries)	of			
DATE								
				ME TACH 210.7 HOBBS 232.9				
	R	EPLACED !	R/H AND L/H	ANNUAL INSPECTION ON FLOATS. REPLACED MISSING PLACARD P/N 12A3-7335 /H AND L/H NOSE GEAR ACTUATOR WITH NEW P/N D68194-A-22. LEFT MLG DOWN WITCH ADJUSTED. ALL LEAK AND GEAR CHECKS SATISFACTORY.				
	W F P	VAS REPAI	RED AND IN AVIATION A OF THE REPA	ME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE USPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE DAMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. AIR ARE ON FILE AT THIS REPAIR STATION UNDER DATE DATE				
	s	IGNED _	20	NO. RJWR390K				
	F	EBRUARY	1, 2004 N179	ME TACH: 210.7				
				CE LETTER #61 BY THE INSTALLATION OF SERVICE KIT #42 LANDING T SATISFACTORY. FLOAT S/N 34069 AND 34070.				
	V F P	VAS REPAI EDERAL ERTINENT	IRED AND IN AVIATION A OF THE REPA	ME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE SPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. AIR ARE ON FILE AT THIS REPAIR STATION UNDER				
	s	V/O NO. <u>62</u> SIGNED FOR WIPAIR	Au C	DATE 4/1/04 JASON T. Exiktson NO. RJWR390K				

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Entries must b	n of Inspections, Tests, Repairs and Alterations endorsed with Name, Rating and Certificate Number of Repair Facility. (See back pages for other specific entries					
DATE										
				MAINTENANCE	LOG SUPPLEMENT					
	F	L.I. Ma Ronkonkor Phone:	ND AIR S cArthur Airp ma, New Yo (631) 588-54	ERVICE port rk 11779	Aircraft Registration No. NTTYME Tach Time 372. Oserial No. 20608184 Date 2.17.05					
	Ce Sid	on ple solicies on mo	ted in	ip Air Ser	SP IIAIW FAR 43APPD rvice Manuals. Replaced Sr PIND-90929-A.4					
	- N - C									
	In:	ip. and	that the were	nose thoats	s were Insp. Ilalw an Annual be in an airworthy Condition—					
		6								
	Si	gned 🚤	rec	ducero	Certificate No. A-P113626668 IA					

YEAR:	REC' TAC TIM	MODERN AERO, INC. 14801 PIONEER TRAIL EDEN PRAIRIE, MN 55347	d Alterations ite Number of pecific entries.)
DATE		952-941-2595	_
		FAA APPROVED REPAIR STATION MZER198L	
		N179ME DATE: 4/19/06 TACH: 0.0	
		INSPECTED FLOATS PER WIPLINE CHECKLIST. REPLACED AFT RETRACT CABLE FOR RIGHT WATER RUDDER. REPLACED MISSING EXTENSION SPRING ON RIGHT WATER RUDDER. REMOVED AND REPLACED LEFT AND RIGHT MAIN GEAR ACTUATORS, REF. WIPLINE SERVICE MANUAL 6.2. COPLIED WITH SL68 BY REWEIGHTING AC WHILE ON FLOATS. I CERTIFY THESE FLOATS HAVE BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN	
	1	AIRWORTHY CONDITION.	
		REFERENCE MODERN AERO W/O# 34013.	O-
	\vdash	BRUCE BEHRENS Bruce Behrans	
		MODERN AERO, INC. 14801 PIONEER TRAIL EDEN PRAIRIE, MN 55347 952-941-2595	
		FAA APPROVED REPAIR STATION MZER198L	
]	N179ME DATE: 5/1/06 TACH: 2.3	
		ADJUSTED RIGHT NOSE GEAR UP PROX SWITCH PER WIPLINE 3450 SERVICE MANUAL 7.3. REFERENCE MODERN AERO W/O# 34147.	
]	BRUCE BEHRENS Bruce Behrons	

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
		Inspected to nose gear L/H gear & Replaced of	loats per Wip actuator. Rep main gear pe	79ME Tach: 65.3 ACTT: 545.0 EngTT: 545.0 PTT:475.0 Iline checklist. Replaced L/H float forward bulkhead, nose gear box and placed both main gear actuators. Serviced hydraulic resevoir. Rigged er Wipline manual. Gear retraction test - ok. Serviced wheel bearings. Trace on R/H main wheel. Approved for return to serviceEND Seaplane Services Surfside Seaplane Base LINO LAKES, MINNESOTA 651-792-4703
		Install on bo		SURP'SIDE SEAPLANE BASE LINO LAKES, MINNIESOTA 651-792-4703

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Inspected f resevoir. R Serviced w	loats per Wigged L/H &	fipline checklis R/H nose ge gs. Approve	h: 175 ACTT: 655 EngTT: 655 PTT:585 st. Replaced R/H nose gear actuator. Serviced hydraulic ear switches per Wipline manual. Gear retraction test - ok. d for return to serviceEND Seaplane Services Surfside Seaplane Base LINO LAKES, MINNESOTA 651-792-4703
	Inspected a Replaced all reservoir, che	nd serviced L/H brake lirecked screen d. Ran gear	floats per Winings. Reseale ins and changed through several	229 ACTT: 709 EngTT: 709 PTT: 639 ipline checklist. ad both brake wheel cylinders and bled system. Removed defluid in power pack. Resealed with new o-ring and stat-o-seal. all fault free cylcles including hand pump operation. Seaplane Services SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA 651-792-4703

15	llert	oump oper		Sa	aplane	Servic	ces
		son A&P3	137958	SURF	SIDE SEAPLANE BAS D LAKES, MINNESOT 651-782-4703		
Date:4-	13-12 F	Reg #:N17	9ME Tac	h:332	Float T1	:704	2
		per Wipli					
		ed and greatings. Re			•		ks.
	_	jear shimr der travel.				_	free
cycles i	ncluding	hand pur 933. Repla	mp operat	ion. Inst	alled W		
Cable K	1 1	16	acca wate			ervices	L
Me	16.						
Mike K	zehni A/I	P 2662300	0	SURFSIDE SI LINO LAKES 651-7	APLANE BASE MINNESOTA 12-4703		
		P 2662300		SURFSIDE SI LINO LAKES 6S1-7	PAPLANE BASE MINNESIOTA 12-4703		
				SURFSIDE SI LINO LAKES 6S1-7	PAPLANE BASE MINNESOTA 12-4703		
				SURFSIDE SI LINO LAKES 651-7	APLANE BASE MINNESOTA 12-4703		
				SURFRIDE SI LINO LAKES 651-7	APLANE BASE I MINNESOTA IZ-4703		
				SURFRIDE SI LINO LAKES 651-7	APLANE BASE I MINNESOTA IZ-4703		
				SURFESIDE SI LINO LAKES 651-7	APLANE BASE I MINNESOTA IZ-4703		

TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		out of specific entries.)
Insperesev trolley include spread Bled	cted floats ior. Service blocks. Rading hand p der compa brakes.	per Wipline checklist. Serviced Hydraulic ed all bearings. Replaced left nose gear an gear through several fault free cycles cump operation. Replaced four hoses @ front artments. Replaced brake hoses at wheels. Seaplane Services Supplied Services SP2699420 SUPPLIES SERVICES SUPPLIES SERVICES
	Date: Inspereseve trolley include spread Bled	Date: 4-26-13 For Inspected floats resevior. Service trolley blocks. Raincluding hand p

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT		Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)			
DATE							
	Inspected Serviced It Cleaned a Replaced Replaced Replaced Replaced Replaced Ran gear	floats per Waydraulic res and greased main brake left nose what right front float all internal float	/ipline checklist servoir. main bearings discs 164-2450 leel D-30380 at toat bumper 30/ loat rigging pull eral fault free c	00 and pads 066-10500. and nose gear bearings A4138 and A4050 . A01000-365.			

YEAR:	RECOI TACH TIME	Inspected floats per Wipline checklist.	Alterations Number of scific entries.)
DATE		Cleaned and greased main bearings. Replaced nose gear bearings A4138 and A4050. Disassembled, cleaned and inspected main gear. Replaced coupling assembly 2ea 30A05000-038, bolt 2 ea NAS6210-52, bushing 1ea 30A04475-006. Adjusted main gear up and down rigging per service maunual. Reinstalled floats on aircraft. Aired tires and bled brakes. Serviced hydraulic reservoir fluid. Ran gear through several fault free cycles including hand pump operation. All indications normal. Seaplane Services Surfside Seaplane Services LINO LAKES, MINNESOTA 651-792-4703	

September 1

Inspected floats per Wipline checklist. Greased main bearings. Replaced nose gear bearings A4138 and Replaced right nose tire and tube. Aired tires and checked brakes. Checked hydraulic reservoir fluid.	to 567 ACTT: 1047 EngTT: 1047 PTT: 977 d A4050. ycles including hand pump operation. All indications normal	Repairs and Alterations ag and Certificate Number of ges for other specific entries.)
Robert Timm A&P2699420	SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA 651-792-4703	

D	Date: 4-1-2017 Reg#: N179ME Tach: 615 ACTT: 1095 EngTT: 1095 PTT: 1025 Inspected floats per Wipline checklist. Replaced all nose gear trolley blocks 3A07604-001. Greased main bearings. Replaced nose gear bearings A4138 and A4050. Replaced left nose tire and tube. Aired tires and checked brakes. Checked hydraulic reservoir fluid. Cycled gear through several fault free cycles including hand pump operation. All indications normal.	epairs and Alterations and Certificate Number of s for other specific entries.)
	Mike Kuehni, A&P2662300 Seaplane Services Surfside Seaplane Base LINO LAKES, MINNESOTA 651-792-4703	

Inspected floats per Wipline checklist. Serviced main and nose bearings. Aired tires and checked brakes. Replaced RH brake linings 066-10500. Replaced LH rear bulkhead 34A01000. Checked hydraulic reservoir fluid. Cycled gear through several fault free	Repairs and Alterations and Certificate Number of ges for other specific entries.) mal.	
Mike Kuehni, A&P2662300	Seaplane Services SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA 651-792-4703	

YEAR:	Date: 5-3-2019 Reg#: N179ME Tach: 720 ACTT: 1200 EngTT: 1200 PTT: 1130				rs and Alteration certificate Number of other specific entries
	Inspected float	office opcome chine			
DATE					
	Replaced main tires and tubes 6.00 x 6 8ply Condor 072-317-0. Aired tires and checked brakes.				
	Checked hydraulic reservoir fluid.				
				es including hand pump operation. All indications normal	() () () () () () () () () ()
	7	100			
	7.0			Seaplane Services	· ·
	Robert Timm A	&P2699420			(
				SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA	
				651-792-4703	-
	1			23	
					-
	1				_
				: 2	
					-
	4			Y	
	+				
	1		1		

	ate: 4-21-2020 Reg#: N179ME Tach: 776 ACTT: 1256 EngTT: 1256 PTT: 1186 aspected floats per Wipline checklist.	Repairs and Alteration and Certificate Number of es for other specific entries.
	erviced nose bearings. Replaced RH nose bearings and races.	
	eplaced LH nose gear actuator 1002572 iaw SL97.	
A	ired tires and checked brakes.	
S	erviced hydraulic reservoir fluid.	
C	ycled gear through several fault free cycles including hand pump operation. All indications normal.	
	7 . Y -	
	short Timm A&P2600420 Seaplane Services	
R	ODER TIMIT ANT 2033420	
	SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA	
_	651-792-4703	
-		
	Date: 1-8-2021 Reg #: N179ME Tach: 800	
	Date: 1 0 2021 110g	
	Removed Wipline amphib 3450 floats S/N 34069 and 34070.	
	Reinstalled landing gear. Aired tires and bled brakes.	
1	Serviced nose strut with nitrogen. Reset flap swith for 40	-
	degrees travel. Reset stall switch to landplane position.	
	See landplane W&B.	
	Seaplane Services	
_	SURFSIDE SEAPLANE BASE	Α.
1	LINO LAKES, MINNESOTA	
	Robert Timm, A&P2699420 651-792-4703	