



PROPELLER LOGBOOK

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	DESCRIPTION OF THE WORK PERFORMED
	HOURS	HOURS	
			TACH READS 2675:39
12-6-94	826:62	"0"	INSTALLED THIS PROPELLOR ON MOONEY M20-J "N" 3895H. AFTER OVERHAUL - YELLOW TAG ISSUED SIDE END OF BOCK. - GROUND RUN OPS CHECK SATISFACTORY -

**El Paso Aero, Inc.
Avionics Associates**

7305 Boeing Drive
El Paso, Texas 79925
FAA CRS # VLIR562K
(915) 779-3481

N# <u>N3875H</u>	Mfg. <u>Mooney</u>	Model <u>M20J</u>	
S/N <u>24-0970</u>	W.O. # <u>54808</u>	DATE <u>03/15/06</u>	
TACH/HOBBS: <u>2855.08</u>	ACFT TOT: <u>2855.08</u>	ENG. TOT: <u>179.7 SMOH</u>	

Routine maintenance performed in conjunction with a 100 Hour Inspection. Cleaned, dressed and painted propeller as required. Pertinent details of work performed are on file at this agency under WO#54808. I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and is airworthy for return to service.

Benito Rivas



